

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
1001.5.1- P1	INOPERABLE FIRE SPRINKLER/STANDPIPE/FIRE ALARM,ETC	\$ 100.00
1001.5.1- P2	IMPROPER SPACING OF FIRE PROTECTION/EXTINGUISHING	\$ 100.00
1001.5.2- P1	FIRE PROTECTION OR EXTINGUISH SYSTEM NOT INSPECTED	\$ 100.00
1001.5.2- P2	AUTO FIRE PROTECTION OR EXTINGUISH SYSTEM NOT	\$ 100.00
1001.5.3	FAILURE TO NOTIFY THE FIRE CHIEF/GFD SYSTEMS OUT	\$ 100.00
1001.7.1	CONCEALMENT AND OBSTRUCTION AND/OR IMPAIRMENT	\$ 100.00
1001.7.2	NO CLEAR SPACE AROUND HYDRANT	\$ 100.00
1001.7.3	STANDPIPE HOSE STATIONS, OUTLETS AND PORTABLE EXT	\$ 100.00
1001.7.4	FIRE ALARM INITIATING DEVICES, SIGNALING DEVICES,	\$ 100.00
1001.8	EQUIPMENT AND HYDRANT NOT CLEARLY MARKED	\$ 100.00
1006.1	NO VENT HOOD & DUCT SYSTEM	\$ 100.00
1006.2.1	NO APPROVED AUTOMATIC FIRE EXTINGUISH SYSTEM	\$ 100.00
1006.2.3.1	EXTENT OF PROTECTION OR AUTO EXTINGUISH SYSTEM	\$ 100.00
1006.2.4.1P1	NO AUTOMATIC, FUEL, OR ELECTRIC SHUT-OFF	\$ 100.00
1006.2.4.1P2	MANUALLY OPERATED RESET SHUTOFF VALVE OR SWITCHES	\$ 100.00
1006.2.8- P1	DEFECT VENT SYSTEM NO CLASSIFIED GREASE FILTERS	\$ 100.00
1006.2.8- P2	GREASE EXTRACTOR NOT UTILIZED OR DEFECTIVE	\$ 100.00
1006.2.8- P3	HOOD AND DUCT SYSTEM NOT PROPERLY CLEANED	\$ 100.00
1006.2.8- P4	EXTINGUISH SYSTEM NOT INSPECTED	\$ 100.00
1006.2.8- P5	FUSIBLE LINK AND AUTO SPRINKLER HEADS NOT REPLACED	\$ 100.00
1007.2.1.1	NO APPROVED FIRE ALARM SYSTEM INSTALLED	\$ 100.00
1007.3.2	UNLISTED OR UNAPPROVED FIRE PROTECT AND COMPONENTS	\$ 100.00
1007.3.3.1	INSUFFICIENT OR LACK OF MANUAL FIRE ALARM SYSTEMS	\$ 100.00
1007.3.3.2	NO ACCESS TO FIRE ALARM CONTROL UNITS	\$ 100.00
1007.3.4.1	NO FIRE ALARM ACCEPTANCE & CERTIFICATION DOCUMENTS	\$ 100.00
101.2	FAIL TO COMPLY W/NATIONALLY RECOGNIZED STANDARDS	\$ 100.00
103.1.1	FAILURE TO UTILIZE PROFESSIONAL ENGINEERS, SPEC	\$ 100.00
104.1.2	OBSTRUCTION OF FIRE SCENE OPERATIONS	\$ 100.00
105	FAILURE TO OBTAIN A PERMIT	\$ 100.00
105.7 -SS1	PERMIT UTILIZED BY UNAUTHORIZED PERSON	\$ 100.00
105.7 -SS2	PERMIT UTILIZED BY UNAUTHORIZED LOCATION	\$ 100.00
105.7 -SS3	FAILURE TO FOLLOW CONDITIONS OF PERMIT	\$ 100.00
105.7 -SS4	FAILURE/REFUSAL OR NEGLIGENCE TO COMPLY	\$ 100.00
105.7 -SS5	FALSE STATEMENT OR MISREPRESENTATION IN APPLICATN	\$ 100.00
105.7 -SS6	PERMIT ISSUED IN ERROR OR IN VIOLATION OF	\$ 100.00
105.8 -SSA.1	FAILURE TO OBTAIN PERMIT FOR AEROSOL PRODUCTS	\$ 100.00
105.8 -SSA.2	FAILURE TO OBTAIN PERMIT FOR AIRCRAFT REFEULING	\$ 100.00
105.8 -SSA.3	FAILURE TO OBTAIN PERMIT FOR AIRCRAFT REPAIR HANGER	\$ 100.00
105.8 -SSA.4	FAILURE TO OBTAIN PERMIT FOR ASBESTOS REMOVAL	\$ 100.00
105.8 -SSA.5	FAILURE TO OBTAIN PERMIT FOR AUTOMOBILE WRECKING	\$ 100.00
105.8 -SSB.1	FAILURE TO OBTAIN PERMIT FOR A BATTERY SYSTEM	\$ 100.00
105.8 -SSB.2	FAILURE TO OBTAIN PERMIT FOR BOWLING PIN OR ALLEY	\$ 100.00
105.8 -SSC.1	FAILURE TO OBTAIN PERMIT FOR CANDLES OR OPEN FLAME	\$ 100.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
105.8 -SSC.2	FAILURE TO OBTAIN PERMIT FOR CARNIALS AND FAIRS	\$ 100.00
105.8 -SSC.3	FAILURE TO OBTAIN PERMIT FOR CELLULOSE NITRATE	\$ 100.00
105.8 -SSC.4	FAILURE TO OBTAIN PERMIT FOR CELLULOSE NITRATE	\$ 100.00
105.8 -SSC.5	FAILURE TO OBTAIN PERMIT FOR COMBUSTIBLE FIBER	\$ 100.00
105.8 -SSC.6	FAILURE TO OBTAIN PERMIT FOR COMBUSTIBLE MATERIAL	\$ 100.00
105.8 -SSC.7	FAILURE TO OBTAIN PERMIT FOR COMPRESSED GASES	\$ 100.00
105.8 -SSC.8	FAILURE TO OBTAIN PERMIT FOR COMMERCIAL RUBBISH-HAUL	\$ 100.00
105.8 -SSC.9	FAILURE TO OBTAIN PERMIT FOR CRYOGENS	\$ 100.00
105.8 -SSD.1	FAILURE TO OBTAIN PERMIT FOR DRY CLEANING PLANTS	\$ 100.00
105.8 -SSD.2	FAILURE TO OBTAIN PERMIT FOR DUST PRODUCING	\$ 100.00
105.8 -SSE.1	FAILURE TO OBTAIN PERMIT FOR EXPLOSIVES OR BLASTING	\$ 100.00
105.8 -SSF.1	FAILURE TO OBTAIN PERMIT FOR FIRE HYDRANTS	\$ 100.00
105.8 -SSF.2	FAILURE TO OBTAIN PERMIT FOR FIREWORKS	\$ 100.00
105.8 -SSF.3	FAILURE TO OBTAIN PERMIT FOR FLAMMABLE OR COMBUSTIBLE	\$ 100.00
105.8 -SSF.4	FAILURE TO OBTAIN PERMIT FOR FRUIT RIPENING	\$ 100.00
105.8 -SSF.5	FAILURE TO OBTAIN PERMIT FOR FUMIGATION OR THERMAL	\$ 100.00
105.8 -SSH.1	FAILURE TO OBTAIN PERMIT FOR HAZARDOUS MATERIALS	\$ 100.00
105.8 -SSH.2	FAILURE TO OBTAIN PERMIT FOR HIGH-PILED COMBUSTIBLES	\$ 100.00
105.8 -SSH.3	FAILURE TO OBTAIN PERMIT FOR HOT-WORK OPERATIONS	\$ 100.00
105.8 -SSL.1	FAILURE TO OBTAIN PERMIT FOR LIQUIFIED PETROLEUM	\$ 100.00
105.8 -SSL.2	FAILURE TO OBTAIN PERMIT FOR LIQUID OR GAS FUELED	\$ 100.00
105.8 -SSL.3	FAILURE TO OBTAIN PERMIT FOR LUMBER YARDS	\$ 100.00
105.8 -SSM.1	FAILURE TO OBTAIN PERMIT FOR MAGNESIUM WORKING	\$ 100.00
105.8 -SSM.2	FAILURE TO OBTAIN PERMIT FOR MALL COVERED	\$ 100.00
105.8 -SSM.3	FAILURE TO OBTAIN PERMIT FOR MOTOR VEHICLE FUEL	\$ 100.00
105.8 -SSO.1	FAILURE TO OBTAIN PERMIT FOR OPEN BURNING	\$ 100.00
105.8 -SSO.2	FAILURE TO OBTAIN PERMIT FOR OPEN BURNING	\$ 100.00
105.8 -SSO.3	FAILURE TO OBTAIN PERMIT FOR OVENS, INDUSTRIAL	\$ 100.00
105.8 -SSP.1	FAILURE TO OBTAIN PERMIT FOR PARADE FLOATS	\$ 100.00
105.8 -SSP.2	FAILURE TO OBTAIN PERMIT FOR PLACES OF ASSEMBLY	\$ 100.00
105.8 -SSP.3	FAILURE TO OBTAIN PERMIT FOR PYROTECHNICAL SPECIAL	\$ 100.00
105.8 -SSR.1	FAILURE TO OBTAIN PERMIT FOR RADIOACTIVE MATERIALS	\$ 100.00
105.8 -SSR.2	FAILURE TO OBTAIN PERMIT FOR REFRIGERATION EQUIPMENT	\$ 100.00
105.8 -SSR.3	FAILURE TO OBTAIN PERMIT FOR REPAIR GARAGES	\$ 100.00
105.8 -SSS.1	FAILURE TO OBTAIN PERMIT FOR SPRAYING OR DIPPING	\$ 100.00
105.8 -SST.1	FAILURE TO OBTAIN PERMIT FOR TEMPOARY MEMBRANE	\$ 100.00
105.8 -SST.2	FAILURE TO OBTAIN PERMIT FOR TIRE STORAGE	\$ 100.00
105.8 -SSW.1	FAILURE TO OBTAIN PERMIT FOR WOOD PORDUCTS	\$ 100.00
1101.1	GENERAL SAFETY PRECAUTIONS NOT PRACTICED	\$ 100.00
1101.3 - P1	NO PERMIT ISSUED AS REQUIRED	\$ 100.00
1101.3 - P2	NO PLAN SHOWING LOCATION/DIMENSIONS OR TIRE	\$ 100.00
1102.2.2	FREE STANDING INCINERATORS IMPROPERLY CONSTRUCTED	\$ 100.00
1102.2.3	FREE STANDING INCINERATORS IMPROPERLY LOCATED/BLDG	\$ 100.00
1102.2.4	INCINERATORS NOT PROPERLY MAINTAINED	\$ 100.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
1102.3.2	NO OPEN BURNING NOTIFICATION TO GUAM FIRE DEPT	\$ 100.00
1102.3.3	NO OPEN BURNING OF PAPER PRODUCTS	\$ 100.00
1102.3.4	TIME & ATMOSPHERIC RESTRICTIONS	\$ 100.00
1102.3.5	MINIMUM DISTANCE REQUIREMENT FOR OPEN BURNING	\$ 100.00
1102.3.6	NO FIRE EXT EQUIPMT AVAILABLE AT OPEN BURNING SITE	\$ 100.00
1102.3.7	UNATTENDED OPEN BURNING	\$ 100.00
1103.2.1.3	UNAPPROVED CONTAINERS FOR STORAGE OF OILY RAGS	\$ 100.00
1103.3.5	OUTSIDE STORAGE	\$ 100.00
1103.3.5.1	OUTSIDE STORAGE OF COMBUSTIBLE MATERIALS LOCATED	\$ 100.00
1103.3.6.2	STORAGE OF INDIVIDUAL PILES OF TIRES IN EXCESS	\$ 100.00
1103.3.6.3	IMPROPER SPACING (CLEAR SPACE LESS THAN 40 FEET)	\$ 100.00
1109.1	IGNITION SOURCES NOT IN COMPLIANCE WITH SECT 1109	\$ 100.00
1109.2	IMPROPER CLEARANCE BETWEEN IGNITION SOURCES	\$ 100.00
1109.3	PORTABLE OR OPEN FLAME DEVICES IMPROPERLY ENCLOSED	\$ 100.00
1109.4	SMOKING	\$ 100.00
1109.4.1	DESIGNATED AREAS - NO SMOKING SIGNS	\$ 100.00
1109.4.2	CONTROLLED USE (HAZARDOUS ENVIRONMENT CONDITIONS)	\$ 100.00
1109.5	IMPROPER DISCARDED BURNING OBJECTS	\$ 100.00
1109.6	IMPROPER DISCARDED HOT ASHES & SPONT IGNITION SRCS	\$ 100.00
1109.7	CHIMNEYS NOT MAINTAINED/UTILIZED WITH SPARK	\$ 100.00
1109.8.2	USE OF CANDLES & OPEN FLAME & DECORATIVE DEVICES	\$ 100.00
1109.8.2-S10	SHADES (IF USED) NOT MADE OF NON-COMBUSTIBLE	\$ 100.00
1109.8.2-SS1	CLASSES I AND II LIQUIDS AND L.P. GAS SHALL NOT BE	\$ 100.00
1109.8.2-SS2	LIQUID-OR SOLID-FUELED LIGHTING DEVICES MORE THAT	\$ 100.00
1109.8.2-SS3	DEVICES OR HOLDER NOT PREVENTING THE SPILLAGE OF	\$ 100.00
1109.8.2-SS4	THE DEVICE OR HOLDER NOT RETURNING TO ITS UPRIGHT	\$ 100.00
1109.8.2-SS5	FLAME NOT ENCLOSED	\$ 100.00
1109.8.2-SS6	CHIMNEYS NOT MADE OF NONCOMBUSTIBLE MATERIALS AND/	\$ 100.00
1109.8.2-SS7	FUEL CANISTERS NOT SAFELY SEALED FOR STORAGE	\$ 100.00
1109.8.2-SS8	STORAGE/HANDLING OF COMBUSTIBLE MATERIALS NOT IN	\$ 100.00
1109.8.2-SS9	SHADES (IF USED) NOT MADE OF NON-COMBUSTIBLE	\$ 100.00
1109.8.3	DURING RELIGIOUS CEREMONIES,LIGHTED HANDHELD CNDLS	\$ 100.00
1109.8.4	ADEQUATE SAFETY PRECAUTIONS-THEATRICAL PERFORMACES	\$ 100.00
1109.9.1	FLAMING FOOD & BEV PREPARATION	\$ 100.00
1109.9.2	IMPROPER DISPENSING OF FLAMMABLE & COMBUSTIBLE LIQ	\$ 100.00
1109.9.2.1	CONTAINERS IMPROPERLY OR NOT SECURED	\$ 100.00
1109.9.2.2	IMPROPER SERVING OF FLAMING FOODS OR BEVERAGES	\$ 100.00
1109.9.3	FLAMING FOODS/BEVERAGES NOT PREPARED NEXT TO TABLE	\$ 100.00
1109.9.4	PREPARER OF FLAMING FOOD/BEVERAGE DOESNT HAVE WET	\$ 100.00
1110.2	FAILURE TO REMOVE ALL COMB & HAZARD MATERIALS	\$ 100.00
1110.3 - P1	NO ACCUMULATION OF COMBUSTIBLE OR HAZARDOUS MATERL	\$ 100.00
1110.3 - P2	VACANT BLDG/PROPERTY NOT MAINTAINED/SECURED	\$ 100.00
1111.2.1	REQUIRED FIRE ASSEMBLIES NOT MAINTAINED/IDENTIFIED	\$ 100.00
1111.2.2	FIRE ASSEMBLIES OBSTRUCTED/IMPAIRED FROM PROPER	\$ 100.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
1203	MEANS OF EGRESS OBSTRUCTED OR RENDERED HAZARDOUS	\$ 100.00
1204.1	AISLES NOT PROVIDED FROM ALL OCCUPIED PORTIONS	\$ 100.00
1204.2.1	AISLE WIDTH NOT IN ACCORDANCE WITH SECTION 1204.2	\$ 100.00
1204.2.2-SS1	IN AREAS SERVING EMPLOYEES ONLY, MINIMUM WIDTH 24	\$ 100.00
1204.2.2-SS2	IN PUBLIC AREAS OF GROUPS B AND M CLEAR AISLE WIDT	\$ 100.00
1205	FAILURE TO MAINTAIN FIRE ESCAPES IF APPROVED	\$ 100.00
1206	EMERGENCY ESCAPE OR RESCUE WINDOWS, DOORS OR WELLS	\$ 100.00
1207.2A	EXIT DOORS NOT PIVOTED/SIDE SWINGING TYPE	\$ 100.00
1207.2B	EXIT DOORS NOT SWINGING IN DIRECTION OF TRAVEL	\$ 100.00
1207.2C	EXIT DOORS NOT SWINGING TO FULL-OPEN POSITION	\$ 100.00
1207.3 -P1	UNABLE TO OPEN EXIT DOOR W/O KEY/EFFORT A/O EXIT	\$ 100.00
1207.3 -P2	MANUALLY OPERATED EDGE-OR SURFACE-MOUNTED FLUSH	\$ 100.00
1207.4	IMPROPER INSTALLATION OF PANIC HARDWARE	\$ 100.00
1207.4 - P1	IMPROPERLY INSTALLED PANIC HARDWARE	\$ 100.00
1207.4 - P2	IMPROPERLY INSTALLED PANIC HARDWARE WHEN BALANCE	\$ 100.00
1207.5	IMPROPER/LACK OF MAINTENANCE OF SPECIAL EGRESS	\$ 100.00
1207.6	EXIT DOORS NOT READILY DISTINGUISHABLE OR EASILY	\$ 100.00
1210.2	BARRIERS PROVIDED IN EXIT STAIRWELLS TO PREVENT	\$ 100.00
1210.3	STORAGE PROHIBITED UNDER EXIT STAIRWAYS(SEE EXCPT)	\$ 100.00
1210.4	APPROVED STAIRWAY IDENTIFICATION SIGNS MISUSED	\$ 100.00
1211.1	NO MEANS OF EGRESS ILLUMINATION (GENERAL)	\$ 100.00
1211.2	EMERGENCY POWER EQUIPMENT USED FOR MEANS OF EGRESS	\$ 100.00
1212.2	INADEQUATE OR NO EXIT SIGNS POSTED AS REQUIRED	\$ 100.00
1212.3	IMPROPER EXIT SIGN GRAPHICS AND/OR SIZE	\$ 100.00
1212.4	EXIT SIGNS NOT INTERNALLY/EXTERNALLY ILLUMINATED	\$ 100.00
1212.5	EXIT SIGNS NOT ILLUMINATED AT ALL TIMES	\$ 100.00
1212.6	ADDITIONAL EXIT SIGNS NOT PROVIDED	\$ 100.00
1212.7	ADDITIONAL EXIT SIGNS IMPROPERLY LOCATED	\$ 100.00
1212.8	EXIT SIGNS AND DIRECTIONAL EXIT MARKINGS CONCEALED	\$ 100.00
1213.1	DISCHARGE, DISPERSAL & REFUGE (GENERAL)	\$ 100.00
1213.2	MEANS OF EGRESS PLANS NOT POSTED WHEN REQUIRED	\$ 100.00
1303.1	EMERGENCY PLANS & STAFF TRAINING, FIRE DRILLS	\$ 100.00
1303.4.1	NO EMERGENCY PLANS PROVIDED	\$ 100.00
1303.4.2	EMERGENCY PLANS NOT SUBMITTED TO THE GFD FOR REVIEW	\$ 100.00
1303.4.3	EMERGENCY PLANS NOT REVIEWED ANNUALLY A/O UPDATES	\$ 100.00
2401.2	NO PERMITS FOR USE OF AIRPORTS,HELIPORTS&HELISTOPS	\$ 100.00
2403.2	IMPROPER CLEARANCE FOR HELIPORTS AND HELISTOPS	\$ 100.00
2403.3	NO PROVISIONS MADE FOR THE CONFINEMENT/DRAINAGE	\$ 100.00
2403.5.1	IMPROPER FIRE EXTINGUISHERS (MUST BE MINIMUM 80-B:	\$ 100.00
2501.10.1	INADEQUATE CLEAR WIDTH BETWEEN SEATING ROWS	\$ 100.00
2501.10.1SS1	INADEQUATE CLEAR SPACE FOR ROWS OF SEATING SERVED	\$ 100.00
2501.10.1SS2	INADEQUATE CLEAR SPACE FOR ROWS OF SEATING SERVED	\$ 100.00
2501.10.2	IMPROPER OR NO SEATING BONDING (SEE EXCEPTIONS)	\$ 100.00
2501.12	NON-COMBUSTABLE ASHTRAY OR MATCH RECEIVERS	\$ 100.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
2501.16.1	CAPACITY OF OCCUPANCY NOT PROPELY POSTED	\$ 100.00
2501.16.2	OCCUPANT LOAD EXCEEDED	\$ 100.00
2501.16.3	OVERCROWDING BEYOND THE APPROVED CAPACITY	\$ 100.00
2501.17	CANDLES & OTHER OPEN FLAME DEVICES	\$ 100.00
2501.18	NO EMERGENCY STANDBY PERSONNEL AS NEEDED	\$ 100.00
2501.3	NO PERMIT REQUIRED TO OPERATE A PLACE OF ASSEMBLY	\$ 100.00
2501.8.2	EXIT DOORS FROM GROUP OCCUPANCIES SHALL NOT	\$ 100.00
2501.9.2	IMPROPER AISLE WIDTH IN ASSEMBLY OCCUPANCIES	\$ 100.00
2504.1	OUTDOOR CARNIVALS/FAIRS AND CONCESSION BOOTHS	\$ 100.00
2504.2.2	FIRE APPARATUS ACCESS ROADS NOT PROVIDED	\$ 100.00
2504.2.3.1	FIRE APPLIANCES NOT PROVIDED FOR ENTIRE MIDWAY	\$ 100.00
2504.2.3.2	TRAVEL DISTANCE FOR FIRE EXTINGUISHERS exceed 75ft	\$ 100.00
2504.3.2	IMPROPER CLEARANCE FOR CONCESSION STANDS FOR COOK	\$ 100.00
2504.3.3	IMPROPER OR NO FIRE EXTINGUISHERS PROVIDED	\$ 100.00
2504.4.2.A	INADEQUATE FUEL TANK CAPACITY IN REFERENCE	\$ 100.00
2504.4.2.B	REFUELING TANK WHILE RIDE IN USE	\$ 100.00
2504.4.3	INTERNAL COMBUSTION POWER SOURCES IMPROPERLY/NOT	\$ 100.00
2504.4.4	IMPROPER OR NO FIRE EXTINGUISHER PROVIDED	\$ 100.00
2901.2	NO SERVICE/REPAIR GARAGE PERMIT	\$ 100.00
2901.3.1	NOT FOLLOWING PROPER STORAGE, USE, AND HANDLING	\$ 100.00
2901.3.2	NO TANK SPILL CONTROL	\$ 100.00
2901.4	IMPROPER DISPENSING OF ALL MOTOR VEHICLE FUELS	\$ 100.00
2901.5	INADEQUATE VENTILATION IN ACCORDANCE W/BLDNG CODE	\$ 100.00
2901.6.1	IMPROPER DRAINING OF MOTOR VEHICLE FUEL	\$ 100.00
2901.6.2	IMPROPER STORAGE OF LUBRICATING OIL	\$ 100.00
2901.6.3	IMPROPER OR NO CAP UTILIZED FOR TERMINATED TANK	\$ 100.00
2901.7.1	NO SMOKING/OPEN FLAMES IN AREAS USED FOR SERVICING	\$ 100.00
2901.7.2	IMPROPER WELDING OPERATIONS	\$ 100.00
2901.7.3	IMPROPER STORAGE OF OILY WASTE MATERIALS	\$ 100.00
2902.5.1	IMPROPER/NO VENT IN BLDGS. WITH BASEMENTS OR PITS	\$ 100.00
2902.5.2	IMPROPER/NO VENT PROVIDED IN BUILDINGS W/BASEMENTS	\$ 100.00
3203	TEMP. MEMBRANE STRUCTURES,TENTS&CANOPIES(PERMIT)	\$ 100.00
3205.2	IMPROPER LOCATION & PARKING	\$ 100.00
3208	NO PORTABLE FIRE EXTINGUISHERS	\$ 100.00
4501.3	NO PERMIT AS REQUIRED FOR SPRAYING OR DIPPING	\$ 100.00
4502.1	NO FIRE PROTECTION/SUPPRESSION EQUIPMENT	\$ 100.00
4502.2.1	IMPROPER MATERIALS OF SPRAY BOOTHS	\$ 100.00
4502.2.2	IMPROPER SIZE OF SPRAY BOOTHS	\$ 100.00
4502.2.3	IMPROPER INTERIOR SURFACES OF SPRAY BOOTHS	\$ 100.00
4502.2.5	IMPROPERLY INSTALLED OR NO BAFFLES IN SPRAY BOOTHS	\$ 100.00
4502.2.9	IMPROPER LIGHT FIXTURES IN SPRAY BOOTHS	\$ 100.00
4901.10	NO VISIBLE HAZARD IDENTIFICATION SIGNS POSTED	\$ 100.00
4901.3	NO PERMIT TO CONDUCT HOT WORK	\$ 100.00
4901.4.1	NO FIRE WATCH PROVIDED DURING HOT-WORK ACTIVITIES	\$ 100.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
4901.4.2	ADDITIONAL PERSONNEL NOT ASSIGNED TO FIRE WATCH	\$ 100.00
4901.4.3	NO FIRE EXTINGUISHERS PROVIDED REQUIRED	\$ 100.00
4901.5.2	HOT WORK BEING CONDUCTED IN PROHIBITED AREAS	\$ 100.00
4901.5.3	HOT WORKS AREAS NOT CLEARED OF COMBUSTIBLES	\$ 100.00
4901.5.5	HOT WORK AREAS FLOOR'S NOT PROPERLY KEPT CLEANED	\$ 100.00
4901.6.2	HOT WORK EQUIPMENT NOT INSPECTED BY USER PRIOR TO	\$ 100.00
4901.6.3-SS1	THE HOT WORK SITE NOT CLEAR OF COMBUSTIBLES OR	\$ 100.00
4901.6.3-SS2	EXPOSED CONSTRUCTION IS NOT OF NONCOMBUSTIBLE MATE	\$ 100.00
4901.6.3-SS3	OPENINGS NOT PROTECTED	\$ 100.00
4901.6.3-SS4	FLOORS NOT KEPT CLEANED	\$ 100.00
4901.6.3-SS5	EXPOSED COMBUSTIBLES ON OPPOSITE SIDE OF PARTITION	\$ 100.00
4901.6.3-SS6	FIRE WATCHES NOT ASSIGNED, EQUIPPED, OR TRAINED	\$ 100.00
4901.6.3-SS7	FIRE EXTINGUISHERS NOT VERIFIED AS OPERABLE AND	\$ 100.00
4901.6.4	NO PRE-INSPECTION OR UNSIGNED REPORT BY INDIVIDUAL	\$ 100.00
4901.8.2-SS1	NO EMERGENCY DISCONNECT SWITCH/CIRCUIT BREAKER	\$ 100.00
4901.8.2-SS2	NO "EMERGENCY DISCONNECT" MARKED AND VISIBLE FROM	\$ 100.00
4901.9	NO FIRE PROTECTION IN HOT WORK AREAS	\$ 100.00
5201.10	IMPROPER CLEARANCE FROM WEEDS/GRASS/BRUSH/TRASH/	\$ 100.00
5201.11	IMPROPER OR NO MAINTENANCE OF FUELING SYSTEM	\$ 100.00
5201.3	IMPROPER OR NO PERMIT FOR MOTOR VEHICLE FUEL	\$ 100.00
5201.4.1.1	IMPROPER DISPENSING OF COMBUSTIBLE LIQUIDS, CNG AN	\$ 100.00
5201.4.1.2	DISPENSING DEVICES IMPROPERLY LOCATED	\$ 100.00
5201.4.1.3	BULK PLANT MOTOR VEHICLE DISPENSING STATIONS	\$ 100.00
5201.4.2	IMPROPER CLEARANCE FROM STORAGE VESSELS TO ABOVE	\$ 100.00
5201.5.1	DISPENSING DEVICES IMPROPERLY PROTECTED	\$ 100.00
5201.5.3	EMERGENCY SHUT DOWN DEVICES NOT PROVIDED	\$ 100.00
5201.5.4	ELECTRICAL DISCONNECT SWITCH NOT PROVIDED	\$ 100.00
5201.6.2	ATTENDANTS NOT CONDUCTING PRIMARY FUNCTION	\$ 100.00
5201.6.3	SIGN NOT POSTED IN CONSPICUOUS LOCATION	\$ 100.00
5201.7	ELECTRICAL EQUIPMENT NOT IN ACCORDANCE WITH CODE	\$ 100.00
5201.8	SIGNS NOT POSTED AS REQUIRED WITHIN SIGHT	\$ 100.00
5201.9	PORTABLE FIRE EXTINGUISHERS NOT PROVIDED	\$ 100.00
8503.1	IMPROPER USE OF TEMPORARY WIRING	\$ 100.00
8503.2	USE OF TEMPORARY WIRING EXCEEDS TIME ALLOTTED	\$ 100.00
8503.3	UNAPPROVED MANNER UTILIZED TO ATTACH TEMPORARY	\$ 100.00
8504	ELECTRICAL HAZARD NOT CORRECTED	\$ 100.00
8505	ELECTRICAL MOTORS NOT MAINTAINED	\$ 100.00
8509.2	ACCESS TO SWITCHBOARDS & PANEL BOARDS	\$ 100.00
8509.3	DOORS TO ELECTRICAL CONTROL PANEL ROOMS	\$ 100.00
8702	NO PERMIT ISSUED TO CONDUCT ASBESTOS-REMOVAL OPS	\$ 100.00
8704.15	ACCESS TO BLDGS/HYDRANTS/OR FIRE APPLIANCES	\$ 100.00
8704.16	NO TELEPHONE PROVIDED FOR EMERGENCY USE	\$ 100.00
8704.2	FIRE DEPARTMENT ACCESS ROADS NOT ESTABLISHED	\$ 100.00
8704.4.1	FIRE PROTECTION NOT PROVIDED DURING CONSTRUCTION	\$ 100.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
8704.4.2	FIRE EXTINGUISHERS NOT PROVIDED DURING CONSTRUCTN	\$ 100.00
8704.4.3.1	IMPROPER OR NO STANDPIPE SYSTEM INSTALLED	\$ 100.00
8704.4.3.2	IMPROPER TEMPORARY STANDPIPE SYSTEM REQUIRED	\$ 100.00
8704.4.3.3	FAILURE TO FOLLOW STANDPIPE INSTALLATION PROCEDURE	\$ 100.00
8704.5	ACCUMULATION OF COMBUSTIBLE DEBRIS	\$ 100.00
8704.8	SMOKING PROHIBITED	\$ 100.00
8705.2 - P1	FIRE PROTECTION SYSTEMS NOT OPERATIONAL	\$ 100.00
8705.2 - P2	FIRE WATCH NOT CONDUCTED WHEN ENTIRE FIRE PROTECTN	\$ 100.00
8705.3	MEANS OF EGRESS NOT MAINTAINED AS REQUIRED	\$ 100.00
8706.2	AUTOMATIC SPRINKLER SYSTEM RENDERED INOPERATIVE	\$ 100.00
8706.3	SUITABLE FIRE HOSE NOT ON SITE AS REQUIRED	\$ 100.00
8706.5	NO BURNING OF COMBUSTIBLE WASTE ON SITE	\$ 100.00
8706.6	NO FIRE WATCH	\$ 100.00
901.1	VIOLATION/FIRE DEPT ACCESS & WATER SUPPLY...	\$ 100.00
901.4.1	IMPROPER OR NO MARKING OF FIRE APPARATUS ACCESS	\$ 100.00
901.4.2	NO APPROVED SIGNS/NOTICES IDENTIFYING FIRE DEPT	\$ 100.00
901.4.3	FIRE PROTECTION EQUIPMENT AND FIRE HYDRANT NOT CLR	\$ 100.00
901.4.4	NO PREMISES IDENTIFICATION	\$ 100.00
901.4.5	STREETS/ROADS NOT IDENTIFIED WITH APPROVED SIGNS	\$ 100.00
902.2.4.1	THE REQUIRED WIDTH OBSTRUCTED AND/OR NOT MAINTAINED	\$ 100.00
902.2.4.2	GATES/BARRIERS IMPROPERLY INSTALLED AND/OR MAINTND	\$ 100.00
903.4.1.2	NO TESTING & MAINT OF FIRE HYDRANT SYSTEMS	\$ 100.00
903.4.1.3	TAMPERING OF FIRE HYDRANTS	\$ 100.00
903.4.3	FIRE HYDRANTS NOT PROTECTED WITH GUARD POSTS	\$ 100.00
903.4.6.1	OBSTRUCTION OF FIRE HYDRANTS	\$ 100.00
UFC3403	REQUIRED PERMIT NOT ISSUED FOR AUTOMOBILE WRECKING	\$ 100.00
UFC3406	IMPROPER ACCUMULATION OF COMBUSTIBLE RUBBISH	\$ 100.00
UFC3407	NO FIRE EXTINGUISHERS PROVIDED AS REQUIRED	\$ 100.00
UFC3408	IMPROPER STORAGE OF TIRES	\$ 100.00
UFC3503	REQUIRED PERMIT NOT ISSUED FOR COVERED MALL BLDGS	\$ 100.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
1001.5.1- P1 - 2nd	INOPERABLE FIRE SPRINKLER/STANDPIPE/FIRE ALARM,ETC	\$ 400.00
1001.5.1- P2 - 2nd	IMPROPER SPACING OF FIRE PROTECTION/EXTINGUISHING	\$ 400.00
1001.5.2- P1 - 2nd	FIRE PROTECTION OR EXTINGUISH SYSTEM NOT INSPECTED	\$ 400.00
1001.5.2- P2 - 2nd	AUTO FIRE PROTECTION OR EXTINGUISH SYSTEM NOT	\$ 400.00
1001.5.3 - 2nd	FAILURE TO NOTIFY THE FIRE CHIEF/GFD SYSTEMS OUT	\$ 400.00
1001.7.1 - 2nd	CONCEALMENT AND OBSTRUCTION AND/OR IMPAIRMENT	\$ 400.00
1001.7.2 - 2nd	NO CLEAR SPACE AROUND HYDRANT	\$ 400.00
1001.7.3 - 2nd	STANDPIPE HOSE STATIONS, OUTLETS AND PORTABLE EXT	\$ 400.00
1001.7.4 - 2nd	FIRE ALARM INITIATING DEVICES, SIGNALING DEVICES,	\$ 400.00
1001.8 - 2nd	EQUIPMENT AND HYDRANT NOT CLEARLY MARKED	\$ 400.00
1006.1 - 2nd	NO VENT HOOD & DUCT SYSTEM	\$ 400.00
1006.2.1 - 2nd	NO APPROVED AUTOMATIC FIRE EXTINGUISH SYSTEM	\$ 400.00
1006.2.3.1 - 2nd	EXTENT OF PROTECTION OR AUTO EXTINGUISH SYSTEM	\$ 400.00
1006.2.4.1P1 - 2nd	NO AUTOMATIC, FUEL, OR ELECTRIC SHUT-OFF	\$ 400.00
1006.2.4.1P2 - 2nd	MANUALLY OPERATED RESET SHUTOFF VALVE OR SWITCHES	\$ 400.00
1006.2.8- P1 - 2nd	DEFECT VENT SYSTEM NO CLASSIFIED GREASE FILTERS	\$ 400.00
1006.2.8- P2 - 2nd	GREASE EXTRACTOR NOT UTILIZED OR DEFECTIVE	\$ 400.00
1006.2.8- P3 - 2nd	HOOD AND DUCT SYSTEM NOT PROPERLY CLEANED	\$ 400.00
1006.2.8- P4 - 2nd	EXTINGUISH SYSTEM NOT INSPECTED	\$ 400.00
1006.2.8- P5 - 2nd	FUSIBLE LINK AND AUTO SPRINKLER HEADS NOT REPLACED	\$ 400.00
1007.2.1.1 - 2nd	NO APPROVED FIRE ALARM SYSTEM INSTALLED	\$ 400.00
1007.3.2 - 2nd	UNLISTED OR UNAPPROVED FIRE PROTECT AND COMPONENTS	\$ 400.00
1007.3.3.1 - 2nd	INSUFFICIENT OR LACK OF MANUAL FIRE ALARM SYSTEMS	\$ 400.00
1007.3.3.2 - 2nd	NO ACCESS TO FIRE ALARM CONTROL UNITS	\$ 400.00
1007.3.4.1 - 2nd	NO FIRE ALARM ACCEPTANCE & CERTIFICATION DOCUMENTS	\$ 400.00
101.2 - 2nd	FAIL TO COMPLY W/NATIONALLY RECOGNIZED STANDARDS	\$ 400.00
103.1.1 - 2nd	FAILURE TO UTILIZE PROFESSIONAL ENGINEERS, SPEC	\$ 400.00
104.1.2 - 2nd	OBSTRUCTION OF FIRE SCENE OPERATIONS	\$ 400.00
105 - 2nd	FAILURE TO OBTAIN A PERMIT	\$ 400.00
105.7 -SS1 - 2nd	PERMIT UTILIZED BY UNAUTHORIZED PERSON	\$ 400.00
105.7 -SS2 - 2nd	PERMIT UTILIZED BY UNAUTHORIZED LOCATION	\$ 400.00
105.7 -SS3 - 2nd	FAILURE TO FOLLOW CONDITIONS OF PERMIT	\$ 400.00
105.7 -SS4 - 2nd	FAILURE/REFUSAL OR NEGLIGENCE TO COMPLY	\$ 400.00
105.7 -SS5 - 2nd	FALSE STATEMENT OR MISREPRESENTATION IN APPLICATN	\$ 400.00
105.7 -SS6 - 2nd	PERMIT ISSUED IN ERROR OR IN VIOLATION OF	\$ 400.00
105.8 -SSA.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR AEROSOL PRODUCTS	\$ 400.00
105.8 -SSA.2 - 2nd	FAILURE TO OBTAIN PERMIT FOR AIRCRAFT REFEULING	\$ 400.00
105.8 -SSA.3 - 2nd	FAILURE TO OBTAIN PERMIT FOR AIRCRAFT REPAIR HANGER	\$ 400.00
105.8 -SSA.4 - 2nd	FAILURE TO OBTAIN PERMIT FOR ASBESTOS REMOVAL	\$ 400.00
105.8 -SSA.5 - 2nd	FAILURE TO OBTAIN PERMIT FOR AUTOMOBILE WRECKING	\$ 400.00
105.8 -SSB.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR A BATTERY SYSTEM	\$ 400.00
105.8 -SSB.2 - 2nd	FAILURE TO OBTAIN PERMIT FOR BOWLING PIN OR ALLEY	\$ 400.00
105.8 -SSC.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR CANDLES OR OPEN FLAME	\$ 400.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
105.8 -SSC.2 - 2nd	FAILURE TO OBTAIN PERMIT FOR CARNIALS AND FAIRS	\$ 400.00
105.8 -SSC.3 - 2nd	FAILURE TO OBTAIN PERMIT FOR CELLULOSE NITRATE	\$ 400.00
105.8 -SSC.4 - 2nd	FAILURE TO OBTAIN PERMIT FOR CELLULOSE NITRATE	\$ 400.00
105.8 -SSC.5 - 2nd	FAILURE TO OBTAIN PERMIT FOR COMBUSTIBLE FIBER	\$ 400.00
105.8 -SSC.6 - 2nd	FAILURE TO OBTAIN PERMIT FOR COMBUSTIBLE MATERIAL	\$ 400.00
105.8 -SSC.7 - 2nd	FAILURE TO OBTAIN PERMIT FOR COMPRESSED GASES	\$ 400.00
105.8 -SSC.8 - 2nd	FAILURE TO OBTAIN PERMIT FOR COMMERCIAL RUBBISH-HAUL	\$ 400.00
105.8 -SSC.9 - 2nd	FAILURE TO OBTAIN PERMIT FOR CRYOGENS	\$ 400.00
105.8 -SSD.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR DRY CLEANING PLANTS	\$ 400.00
105.8 -SSD.2 - 2nd	FAILURE TO OBTAIN PERMIT FOR DUST PRODUCING	\$ 400.00
105.8 -SSE.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR EXPLOSIVES OR BLASTING	\$ 400.00
105.8 -SSF.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR FIRE HYDRANTS	\$ 400.00
105.8 -SSF.2 - 2nd	FAILURE TO OBTAIN PERMIT FOR FIREWORKS	\$ 400.00
105.8 -SSF.3 - 2nd	FAILURE TO OBTAIN PERMIT FOR FLAMMABLE OR COMBUSTIBLE	\$ 400.00
105.8 -SSF.4 - 2nd	FAILURE TO OBTAIN PERMIT FOR FRUIT RIPENING	\$ 400.00
105.8 -SSF.5 - 2nd	FAILURE TO OBTAIN PERMIT FOR FUMIGATION OR THERMAL	\$ 400.00
105.8 -SSH.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR HAZARDOUS MATERIALS	\$ 400.00
105.8 -SSH.2 - 2nd	FAILURE TO OBTAIN PERMIT FOR HIGH-PILED COMBUSTIBLES	\$ 400.00
105.8 -SSH.3 - 2nd	FAILURE TO OBTAIN PERMIT FOR HOT-WORK OPERATIONS	\$ 400.00
105.8 -SSI.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR LIQUIFIED PETROLEUM	\$ 400.00
105.8 -SSI.2 - 2nd	FAILURE TO OBTAIN PERMIT FOR LIQUID OR GAS FUELED	\$ 400.00
105.8 -SSI.3 - 2nd	FAILURE TO OBTAIN PERMIT FOR LUMBER YARDS	\$ 400.00
105.8 -SSM.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR MAGNESIUM WORKING	\$ 400.00
105.8 -SSM.2 - 2nd	FAILURE TO OBTAIN PERMIT FOR MALL COVERED	\$ 400.00
105.8 -SSM.3 - 2nd	FAILURE TO OBTAIN PERMIT FOR MOTOR VEHICLE FUEL	\$ 400.00
105.8 -SSO.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR OPEN BURNING	\$ 400.00
105.8 -SSO.2 - 2nd	FAILURE TO OBTAIN PERMIT FOR OPEN BURNING	\$ 400.00
105.8 -SSO.3 - 2nd	FAILURE TO OBTAIN PERMIT FOR OVENS, INDUSTRIAL	\$ 400.00
105.8 -SSP.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR PARADE FLOATS	\$ 400.00
105.8 -SSP.2 - 2nd	FAILURE TO OBTAIN PERMIT FOR PLACES OF ASSEMBLY	\$ 400.00
105.8 -SSP.3 - 2nd	FAILURE TO OBTAIN PERMIT FOR PYROTECHNICAL SPECIAL	\$ 400.00
105.8 -SSR.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR RADIOACTIVE MATERIALS	\$ 400.00
105.8 -SSR.2 - 2nd	FAILURE TO OBTAIN PERMIT FOR REFRIGERATION EQUIPMENT	\$ 400.00
105.8 -SSR.3 - 2nd	FAILURE TO OBTAIN PERMIT FOR REPAIR GARAGES	\$ 400.00
105.8 -SSS.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR SPRAYING OR DIPPING	\$ 400.00
105.8 -SST.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR TEMPOARY MEMBRANE	\$ 400.00
105.8 -SST.2 - 2nd	FAILURE TO OBTAIN PERMIT FOR TIRE STORAGE	\$ 400.00
105.8 -SSW.1 - 2nd	FAILURE TO OBTAIN PERMIT FOR WOOD PORDUCTS	\$ 400.00
1101.1 - 2nd	GENERAL SAFETY PRECAUTIONS NOT PRACTICED	\$ 400.00
1101.3 - P1 - 2nd	NO PERMIT ISSUED AS REQUIRED	\$ 400.00
1101.3 - P2 - 2nd	NO PLAN SHOWING LOCATION/DIMENSIONS OR TIRE	\$ 400.00
1102.2.2 - 2nd	FREE STANDING INCINERATORS IMPROPERLY CONSTRUCTED	\$ 400.00
1102.2.3 - 2nd	FREE STANDING INCINERATORS IMPROPERLY LOCATED/BLDG	\$ 400.00
1102.2.4 - 2nd	INCINERATORS NOT PROPERLY MAINTAINED	\$ 400.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
1102.3.2 - 2nd	NO OPEN BURNING NOTIFICATION TO GUAM FIRE DEPT	\$ 400.00
1102.3.3 - 2nd	NO OPEN BURNING OF PAPER PRODUCTS	\$ 400.00
1102.3.4 - 2nd	TIME & ATMOSPHERIC RESTRICTIONS	\$ 400.00
1102.3.5 - 2nd	MINIMUM DISTANCE REQUIREMENT FOR OPEN BURNING	\$ 400.00
1102.3.6 - 2nd	NO FIRE EXT EQUIPMT AVAILABLE AT OPEN BURNING SITE	\$ 400.00
1102.3.7 - 2nd	UNATTENDED OPEN BURNING	\$ 400.00
1103.2.1.3 - 2nd	UNAPPROVED CONTAINERS FOR STORAGE OF OILY RAGS	\$ 400.00
1103.3.5 - 2nd	OUTSIDE STORAGE	\$ 400.00
1103.3.5.1 - 2nd	OUTSIDE STORAGE OF COMBUSTIBLE MATERIALS LOCATED	\$ 400.00
1103.3.6.2 - 2nd	STORAGE OF INDIVIDUAL PILES OF TIRES IN EXCESS	\$ 400.00
1103.3.6.3 - 2nd	IMPROPER SPACING (CLEAR SPACE LESS THAN 40 FEET)	\$ 400.00
1109.1 - 2nd	IGNITION SOURCES NOT IN COMPLIANCE WITH SECT 1109	\$ 400.00
1109.2 - 2nd	IMPROPER CLEARANCE BETWEEN IGNITION SOURCES	\$ 400.00
1109.3 - 2nd	PORTABLE OR OPEN FLAME DEVICES IMPROPERLY ENCLOSED	\$ 400.00
1109.4 - 2nd	SMOKING	\$ 400.00
1109.4.1 - 2nd	DESIGNATED AREAS - NO SMOKING SIGNS	\$ 400.00
1109.4.2 - 2nd	CONTROLLED USE (HAZARDOUS ENVIRONMENT CONDITIONS)	\$ 400.00
1109.5 - 2nd	IMPROPER DISCARDED BURNING OBJECTS	\$ 400.00
1109.6 - 2nd	IMPROPER DISCARDED HOT ASHES & SPONT IGNITION SRCS	\$ 400.00
1109.7 - 2nd	CHIMNEYS NOT MAINTAINED/UTILIZED WITH SPARK	\$ 400.00
1109.8.2 - 2nd	USE OF CANDLES & OPEN FLAME & DECORATIVE DEVICES	\$ 400.00
1109.8.2-S10 - 2nd	SHADES (IF USED) NOT MADE OF NON-COMBUSTIBLE	\$ 400.00
1109.8.2-SS1 - 2nd	CLASSES I AND II LIQUIDS AND L.P. GAS SHALL NOT BE	\$ 400.00
1109.8.2-SS2 - 2nd	LIQUID-OR SOLID-FUELED LIGHTING DEVICES MORE THAT	\$ 400.00
1109.8.2-SS3 - 2nd	DEVICES OR HOLDER NOT PREVENTING THE SPILLAGE OF	\$ 400.00
1109.8.2-SS4 - 2nd	THE DEVICE OR HOLDER NOT RETURNING TO ITS UPRIGHT	\$ 400.00
1109.8.2-SS5 - 2nd	FLAME NOT ENCLOSED	\$ 400.00
1109.8.2-SS6 - 2nd	CHIMNEYS NOT MADE OF NONCOMBUSTIBLE MATERIALS AND/	\$ 400.00
1109.8.2-SS7 - 2nd	FUEL CANISTERS NOT SAFELY SEALED FOR STORAGE	\$ 400.00
1109.8.2-SS8 - 2nd	STORAGE/HANDLING OF COMBUSTIBLE MATERIALS NOT IN	\$ 400.00
1109.8.2-SS9 - 2nd	SHADES (IF USED) NOT MADE OF NON-COMBUSTIBLE	\$ 400.00
1109.8.3 - 2nd	DURING RELIGIOUS CEREMONIES,LIGHTED HANDHELD CNDLS	\$ 400.00
1109.8.4 - 2nd	ADEQUATE SAFETY PRECAUTIONS-THEATRICAL PERFORMACES	\$ 400.00
1109.9.1 - 2nd	FLAMING FOOD & BEV PREPARATION	\$ 400.00
1109.9.2 - 2nd	IMPROPER DISPENSING OF FLAMMABLE & COMBUSTIBLE LIQ	\$ 400.00
1109.9.2.1 - 2nd	CONTAINERS IMPROPERLY OR NOT SECURED	\$ 400.00
1109.9.2.2 - 2nd	IMPROPER SERVING OF FLAMING FOODS OR BEVERAGES	\$ 400.00
1109.9.3 - 2nd	FLAMING FOODS/BEVERAGES NOT PREPARED NEXT TO TABLE	\$ 400.00
1109.9.4 - 2nd	PREPARER OF FLAMING FOOD/BEVERAGE DOESNT HAVE WET	\$ 400.00
1110.2 - 2nd	FAILURE TO REMOVE ALL COMB & HAZARD MATERIALS	\$ 400.00
1110.3 - P1 - 2nd	NO ACCUMULATION OF COMBUSTIBLE OR HAZARDOUS MATERL	\$ 400.00
1110.3 - P2 - 2nd	VACANT BLDG/PROPERTY NOT MAINTAINED/SECURED	\$ 400.00
1111.2.1 - 2nd	REQUIRED FIRE ASSEMBLIES NOT MAINTAINED/IDENTIFIED	\$ 400.00
1111.2.2 - 2nd	FIRE ASSEMBLIES OBSTRUCTED/IMPAIRED FROM PROPER	\$ 400.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
1203 - 2nd	MEANS OF EGRESS OBSTRUCTED OR RENDERED HAZARDOUS	\$ 400.00
1204.1 - 2nd	AISLES NOT PROVIDED FROM ALL OCCUPIED PORTIONS	\$ 400.00
1204.2.1 - 2nd	AISLE WIDTH NOT IN ACCORDANCE WITH SECTION 1204.2	\$ 400.00
1204.2.2-SS1 - 2nd	IN AREAS SERVING EMPLOYEES ONLY, MINIMUM WIDTH 24	\$ 400.00
1204.2.2-SS2 - 2nd	IN PUBLIC AREAS OF GROUPS B AND M CLEAR AISLE WIDT	\$ 400.00
1205 - 2nd	FAILURE TO MAINTAIN FIRE ESCAPES IF APPROVED	\$ 400.00
1206 - 2nd	EMERGENCY ESCAPE OR RESCUE WINDOWS, DOORS OR WELLS	\$ 400.00
1207.2A - 2nd	EXIT DOORS NOT PIVOTED/SIDE SWINGING TYPE	\$ 400.00
1207.2B - 2nd	EXIT DOORS NOT SWINGING IN DIRECTION OF TRAVEL	\$ 400.00
1207.2C - 2nd	EXIT DOORS NOT SWINGING TO FULL-OPEN POSITION	\$ 400.00
1207.3 -P1 - 2nd	UNABLE TO OPEN EXIT DOOR W/O KEY/EFFORT A/O EXIT	\$ 400.00
1207.3 -P2 - 2nd	MANUALLY OPERATED EDGE-OR SURFACE-MOUNTED FLUSH	\$ 400.00
1207.4 - 2nd	IMPROPER INSTALLATION OF PANIC HARDWARE	\$ 400.00
1207.4 - P1 - 2nd	IMPROPERLY INSTALLED PANIC HARDWARE	\$ 400.00
1207.4 - P2 - 2nd	IMPROPERLY INSTALLED PANIC HARDWARE WHEN BALANCE	\$ 400.00
1207.5 - 2nd	IMPROPER/LACK OF MAINTENANCE OF SPECIAL EGRESS	\$ 400.00
1207.6 - 2nd	EXIT DOORS NOT READILY DISTINGUISHABLE OR EASILY	\$ 400.00
1210.2 - 2nd	BARRIERS PROVIDED IN EXIT STAIRWELLS TO PREVENT	\$ 400.00
1210.3 - 2nd	STORAGE PROHIBITED UNDER EXIT STAIRWAYS(SEE EXCPT)	\$ 400.00
1210.4 - 2nd	APPROVED STAIRWAY IDENTIFICATION SIGNS MISUSED	\$ 400.00
1211.1 - 2nd	NO MEANS OF EGRESS ILLUMINATION (GENERAL)	\$ 400.00
1211.2 - 2nd	EMERGENCY POWER EQUIPMENT USED FOR MEANS OF EGRESS	\$ 400.00
1212.2 - 2nd	INADEQUATE OR NO EXIT SIGNS POSTED AS REQUIRED	\$ 400.00
1212.3 - 2nd	IMPROPER EXIT SIGN GRAPHICS AND/OR SIZE	\$ 400.00
1212.4 - 2nd	EXIT SIGNS NOT INTERNALLY/EXTERNALLY ILLUMINATED	\$ 400.00
1212.5 - 2nd	EXIT SIGNS NOT ILLUMINATED AT ALL TIMES	\$ 400.00
1212.6 - 2nd	ADDITIONAL EXIT SIGNS NOT PROVIDED	\$ 400.00
1212.7 - 2nd	ADDITIONAL EXIT SIGNS IMPROPERLY LOCATED	\$ 400.00
1212.8 - 2nd	EXIT SIGNS AND DIRECTIONAL EXIT MARKINGS CONCEALED	\$ 400.00
1213.1 - 2nd	DISCHARGE, DISPERSAL & REFUGE (GENERAL)	\$ 400.00
1213.2 - 2nd	MEANS OF EGRESS PLANS NOT POSTED WHEN REQUIRED	\$ 400.00
1303.1 - 2nd	EMERGENCY PLANS & STAFF TRAINING, FIRE DRILLS	\$ 400.00
1303.4.1 - 2nd	NO EMERGENCY PLANS PROVIDED	\$ 400.00
1303.4.2 - 2nd	EMERGENCY PLANS NOT SUBMITTED TO THE GFD FOR REVIEW	\$ 400.00
1303.4.3 - 2nd	EMERGENCY PLANS NOT REVIEWED ANNUALLY A/O UPDATES	\$ 400.00
2401.2 - 2nd	NO PERMITS FOR USE OF AIRPORTS,HELIPORTS&HELISTOPS	\$ 400.00
2403.2 - 2nd	IMPROPER CLEARANCE FOR HELIPORTS AND HELISTOPS	\$ 400.00
2403.3 - 2nd	NO PROVISIONS MADE FOR THE CONFINEMENT/DRAINAGE	\$ 400.00
2403.5.1 - 2nd	IMPROPER FIRE EXTINGUISHERS (MUST BE MINUMUM 80-B:	\$ 400.00
2501.10.1 - 2nd	INADEQUATE CLEAR WIDTH BETWEEN SEATING ROWS	\$ 400.00
2501.10.1SS1 - 2nd	INADEQUATE CLEAR SPACE FOR ROWS OF SEATING SERVED	\$ 400.00
2501.10.1SS2 - 2nd	INADEQUATE CLEAR SPACE FOR ROWS OF SEATING SERVED	\$ 400.00
2501.10.2 - 2nd	IMPROPER OR NO SEATING BONDING (SEE EXCEPTIONS)	\$ 400.00
2501.12 - 2nd	NON-COMBUSTABLE ASHTRAY OR MATCH RECEIVERS	\$ 400.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
2501.16.1 - 2nd	CAPACITY OF OCCUPANCY NOT PROPELY POSTED	\$ 400.00
2501.16.2 - 2nd	OCCUPANT LOAD EXCEEDED	\$ 400.00
2501.16.3 - 2nd	OVERCROWDING BEYOND THE APPROVED CAPACITY	\$ 400.00
2501.17 - 2nd	CANDLES & OTHER OPEN FLAME DEVICES	\$ 400.00
2501.18 - 2nd	NO EMERGENCY STANDBY PERSONNEL AS NEEDED	\$ 400.00
2501.3 - 2nd	NO PERMIT REQUIRED TO OPERATE A PLACE OF ASSEMBLY	\$ 400.00
2501.8.2 - 2nd	EXIT DOORS FROM GROUP OCCUPANCIES SHALL NOT	\$ 400.00
2501.9.2 - 2nd	IMPROPER AISLE WIDTH IN ASSEMBLY OCCUPANCIES	\$ 400.00
2504.1 - 2nd	OUTDOOR CARNIVALS/FAIRS AND CONCESSION BOOTHS	\$ 400.00
2504.2.2 - 2nd	FIRE APPARATUS ACCESS ROADS NOT PROVIDED	\$ 400.00
2504.2.3.1 - 2nd	FIRE APPLIANCES NOT PROVIDED FOR ENTIRE MIDWAY	\$ 400.00
2504.2.3.2 - 2nd	TRAVEL DISTANCE FOR FIRE EXTINGUISHERS exceed 75ft	\$ 400.00
2504.3.2 - 2nd	IMPROPER CLEARANCE FOR CONCESSION STANDS FOR COOK	\$ 400.00
2504.3.3 - 2nd	IMPROPER OR NO FIRE EXTINGUISHERS PROVIDED	\$ 400.00
2504.4.2.A - 2nd	INADEQUATE FUEL TANK CAPACITY IN REFERENCE	\$ 400.00
2504.4.2.B - 2nd	REFUELING TANK WHILE RIDE IN USE	\$ 400.00
2504.4.3 - 2nd	INTERNAL COMBUSTION POWER SOURCES IMPROPERLY/NOT	\$ 400.00
2504.4.4 - 2nd	IMPROPER OR NO FIRE EXTINGUISHER PROVIDED	\$ 400.00
2901.2 - 2nd	NO SERVICE/REPAIR GARAGE PERMIT	\$ 400.00
2901.3.1 - 2nd	NOT FOLLOWING PROPER STORAGE, USE, AND HANDLING	\$ 400.00
2901.3.2 - 2nd	NO TANK SPILL CONTROL	\$ 400.00
2901.4 - 2nd	IMPROPER DISPENSING OF ALL MOTOR VEHICLE FUELS	\$ 400.00
2901.5 - 2nd	INADEQUATE VENTILATION IN ACCORDANCE W/BLDNG CODE	\$ 400.00
2901.6.1 - 2nd	IMPROPER DRAINING OF MOTOR VEHICLE FUEL	\$ 400.00
2901.6.2 - 2nd	IMPROPER STORAGE OF LUBRICATING OIL	\$ 400.00
2901.6.3 - 2nd	IMPROPER OR NO CAP UTILIZED FOR TERMINATED TANK	\$ 400.00
2901.7.1 - 2nd	NO SMOKING/OPEN FLAMES IN AREAS USED FOR SERVICING	\$ 400.00
2901.7.2 - 2nd	IMPROPER WELDING OPERATIONS	\$ 400.00
2901.7.3 - 2nd	IMPROPER STORAGE OF OILY WASTE MATERIALS	\$ 400.00
2902.5.1 - 2nd	IMPROPER/NO VENT IN BLDGS. WITH BASEMENTS OR PITS	\$ 400.00
2902.5.2 - 2nd	IMPROPER/NO VENT PROVIDED IN BUILDINGS W/BASEMENTS	\$ 400.00
3203 - 2nd	TEMP. MEMBRANE STRUCTURES,TENTS&CANOPIES(PERMIT)	\$ 400.00
3205.2 - 2nd	IMPROPER LOCATION & PARKING	\$ 400.00
3208 - 2nd	NO PORTABLE FIRE EXTINGUISHERS	\$ 400.00
4501.3 - 2nd	NO PERMIT AS REQUIRED FOR SPRAYING OR DIPPING	\$ 400.00
4502.1 - 2nd	NO FIRE PROTECTION/SUPPRESSION EQUIPMENT	\$ 400.00
4502.2.1 - 2nd	IMPROPER MATERIALS OF SPRAY BOOTHS	\$ 400.00
4502.2.2 - 2nd	IMPROPER SIZE OF SPRAY BOOTHS	\$ 400.00
4502.2.3 - 2nd	IMPROPER INTERIOR SURFACES OF SPRAY BOOTHS	\$ 400.00
4502.2.5 - 2nd	IMPROPERLY INSTALLED OR NO BAFFLES IN SPRAY BOOTHS	\$ 400.00
4502.2.9 - 2nd	IMPROPER LIGHT FIXTURES IN SPRAY BOOTHS	\$ 400.00
4901.10 - 2nd	NO VISIBLE HAZARD IDENTIFICATION SIGNS POSTED	\$ 400.00
4901.3 - 2nd	NO PERMIT TO CONDUCT HOT WORK	\$ 400.00
4901.4.1 - 2nd	NO FIRE WATCH PROVIDED DURING HOT-WORK ACTIVITIES	\$ 400.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
4901.4.2 - 2nd	ADDITIONAL PERSONNEL NOT ASSIGNED TO FIRE WATCH	\$ 400.00
4901.4.3 - 2nd	NO FIRE EXTINGUISHERS PROVIDED REQUIRED	\$ 400.00
4901.5.2 - 2nd	HOT WORK BEING CONDUCTED IN PROHIBITED AREAS	\$ 400.00
4901.5.3 - 2nd	HOT WORKS AREAS NOT CLEARED OF COMBUSTIBLES	\$ 400.00
4901.5.5 - 2nd	HOT WORK AREAS FLOOR'S NOT PROPERLY KEPT CLEANED	\$ 400.00
4901.6.2 - 2nd	HOT WORK EQUIPMENT NOT INSPECTED BY USER PRIOR TO	\$ 400.00
4901.6.3-SS1 - 2nd	THE HOT WORK SITE NOT CLEAR OF COMBUSTIBLES OR	\$ 400.00
4901.6.3-SS2 - 2nd	EXPOSED CONSTRUCTION IS NOT OF NONCOMBUSTIBLE MATE	\$ 400.00
4901.6.3-SS3 - 2nd	OPENINGS NOT PROTECTED	\$ 400.00
4901.6.3-SS4 - 2nd	FLOORS NOT KEPT CLEANED	\$ 400.00
4901.6.3-SS5 - 2nd	EXPOSED COMBUSTIBLES ON OPPOSITE SIDE OF PARTITION	\$ 400.00
4901.6.3-SS6 - 2nd	FIRE WATCHES NOT ASSIGNED, EQUIPPED, OR TRAINED	\$ 400.00
4901.6.3-SS7 - 2nd	FIRE EXTINGUISHERS NOT VERIFIED AS OPERABLE AND	\$ 400.00
4901.6.4 - 2nd	NO PRE-INSPECTION OR UNSIGNED REPORT BY INDIVIDUAL	\$ 400.00
4901.8.2-SS1 - 2nd	NO EMERGENCY DISCONNECT SWITCH/CIRCUIT BREAKER	\$ 400.00
4901.8.2-SS2 - 2nd	NO "EMERGENCY DISCONNECT" MARKED AND VISIBLE FROM	\$ 400.00
4901.9 - 2nd	NO FIRE PROTECTION IN HOT WORK AREAS	\$ 400.00
5201.10 - 2nd	IMPROPER CLEARANCE FROM WEEDS/GRASS/BRUSH/TRASH/	\$ 400.00
5201.11 - 2nd	IMPROPER OR NO MAINTENANCE OF FUELING SYSTEM	\$ 400.00
5201.3 - 2nd	IMPROPER OR NO PERMIT FOR MOTOR VEHICLE FUEL	\$ 400.00
5201.4.1.1 - 2nd	IMPROPER DISPENSING OF COMBUSTIBLE LIQUIDS, CNG AN	\$ 400.00
5201.4.1.2 - 2nd	DISPENSING DEVICES IMPROPERLY LOCATED	\$ 400.00
5201.4.1.3 - 2nd	BULK PLANT MOTOR VEHICLE DISPENSING STATIONS	\$ 400.00
5201.4.2 - 2nd	IMPROPER CLEARANCE FROM STORAGE VESSELS TO ABOVE	\$ 400.00
5201.5.1 - 2nd	DISPENSING DEVICES IMPROPERLY PROTECTED	\$ 400.00
5201.5.3 - 2nd	EMERGENCY SHUT DOWN DEVICES NOT PROVIDED	\$ 400.00
5201.5.4 - 2nd	ELECTRICAL DISCONNECT SWITCH NOT PROVIDED	\$ 400.00
5201.6.2	ATTENDANTS NOT CONDUCTING PRIMARY FUNCTION	\$ 400.00
5201.6.3 - 2nd	SIGN NOT POSTED IN CONSPICUOUS LOCATION	\$ 400.00
5201.7 - 2nd	ELECTRICAL EQUIPMENT NOT IN ACCORDANCE WITH CODE	\$ 400.00
5201.8 - 2nd	SIGNS NOT POSTED AS REQUIRED WITHIN SIGHT	\$ 400.00
5201.9 - 2nd	PORTABLE FIRE EXTINGUISHERS NOT PROVIDED	\$ 400.00
8503.1 - 2nd	IMPROPER USE OF TEMPORARY WIRING	\$ 400.00
8503.2 - 2nd	USE OF TEMPORARY WIRING EXCEEDS TIME ALLOTTED	\$ 400.00
8503.3 - 2nd	UNAPPROVED MANNER UTILIZED TO ATTACH TEMPORARY	\$ 400.00
8504 - 2nd	ELECTRICAL HAZARD NOT CORRECTED	\$ 400.00
8505 - 2nd	ELECTRICAL MOTORS NOT MAINTAINED	\$ 400.00
8509.2 - 2nd	ACCESS TO SWITCHBOARDS & PANEL BOARDS	\$ 400.00
8509.3 - 2nd	DOORS TO ELECTRICAL CONTROL PANEL ROOMS	\$ 400.00
8702 - 2nd	NO PERMIT ISSUED TO CONDUCT ASBESTOS-REMOVAL OPS	\$ 400.00
8704.15 - 2nd	ACCESS TO BLDGS/HYDRANTS/OR FIRE APPLIANCES	\$ 400.00
8704.16 - 2nd	NO TELEPHONE PROVIDED FOR EMERGENCY USE	\$ 400.00
8704.2 - 2nd	FIRE DEPARTMENT ACCESS ROADS NOT ESTABLISHED	\$ 400.00
8704.4.1 - 2nd	FIRE PROTECTION NOT PROVIDED DURING CONSTRUCTION	\$ 400.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
8704.4.2 - 2nd	FIRE EXTINGUISHERS NOT PROVIDED DURING CONSTRUCTN	\$ 400.00
8704.4.3.1 - 2nd	IMPROPER OR NO STANDPIPE SYSTEM INSTALLED	\$ 400.00
8704.4.3.2 - 2nd	IMPROPER TEMPORARY STANDPIPE SYSTEM REQUIRED	\$ 400.00
8704.4.3.3 - 2nd	FAILURE TO FOLLOW STANDPIPE INSTALLATION PROCEDURE	\$ 400.00
8704.5 - 2nd	ACCUMULATION OF COMBUSTIBLE DEBRIS	\$ 400.00
8704.8 - 2nd	SMOKING PROHIBITED	\$ 400.00
8705.2 - P1 - 2nd	FIRE PROTECTION SYSTEMS NOT OPERATIONAL	\$ 400.00
8705.2 - P2 - 2nd	FIRE WATCH NOT CONDUCTED WHEN ENTIRE FIRE PROTECTN	\$ 400.00
8705.3 - 2nd	MEANS OF EGRESS NOT MAINTAINED AS REQUIRED	\$ 400.00
8706.2 - 2nd	AUTOMATIC SPRINKLER SYSTEM RENDERED INOPERATIVE	\$ 400.00
8706.3 - 2nd	SUITABLE FIRE HOSE NOT ON SITE AS REQUIRED	\$ 400.00
8706.5 - 2nd	NO BURNING OF COMBUSTIBLE WASTE ON SITE	\$ 400.00
8706.6 - 2nd	NO FIRE WATCH	\$ 400.00
901.1 - 2nd	VIOLATION/FIRE DEPT ACCESS & WATER SUPPLY...	\$ 400.00
901.4.1 - 2nd	IMPROPER OR NO MARKING OF FIRE APPARATUS ACCESS	\$ 400.00
901.4.2 - 2nd	NO APPROVED SIGNS/NOTICES IDENTIFYING FIRE DEPT	\$ 400.00
901.4.3 - 2nd	FIRE PROTECTION EQUIPMENT AND FIRE HYDRANT NOT CLR	\$ 400.00
901.4.4 - 2nd	NO PREMISES IDENTIFICATION	\$ 400.00
901.4.5 - 2nd	STREETS/ROADS NOT IDENTIFIED WITH APPROVED SIGNS	\$ 400.00
902.2.4.1 - 2nd	THE REQUIRED WIDTH OBSTRUCTED AND/OR NOT MAINTAINED	\$ 400.00
902.2.4.2 - 2nd	GATES/BARRIERS IMPROPERLY INSTALLED AND/OR MAINTND	\$ 400.00
903.4.1.2 - 2nd	NO TESTING & MAINT OF FIRE HYDRANT SYSTEMS	\$ 400.00
903.4.1.3 - 2nd	TAMPERING OF FIRE HYDRANTS	\$ 400.00
903.4.3 - 2nd	FIRE HYDRANTS NOT PROTECTED WITH GUARD POSTS	\$ 400.00
903.4.6.1 - 2nd	OBSTRUCTION OF FIRE HYDRANTS	\$ 400.00
UFC3403 - 2nd	REQUIRED PERMIT NOT ISSUED FOR AUTOMOBILE WRECKING	\$ 400.00
UFC3406 - 2nd	IMPROPER ACCUMULATION OF COMBUSTIBLE RUBBISH	\$ 400.00
UFC3407 - 2nd	NO FIRE EXTINGUISHERS PROVIDED AS REQUIRED	\$ 400.00
UFC3408 - 2nd	IMPROPER STORAGE OF TIRES	\$ 400.00
UFC3503 - 2nd	REQUIRED PERMIT NOT ISSUED FOR COVERED MALL BLDGS	\$ 400.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
1001.5.1- P1 - 3rd	INOPERABLE FIRE SPRINKLER/STANDPIPE/FIRE ALARM,ETC	\$ 1,000.00
1001.5.1- P2 - 3rd	IMPROPER SPACING OF FIRE PROTECTION/EXTINGUISHING	\$ 1,000.00
1001.5.2- P1 - 3rd	FIRE PROTECTION OR EXTINGUISH SYSTEM NOT INSPECTED	\$ 1,000.00
1001.5.2- P2 - 3rd	AUTO FIRE PROTECTION OR EXTINGUISH SYSTEM NOT	\$ 1,000.00
1001.5.3 - 3rd	FAILURE TO NOTIFY THE FIRE CHIEF/GFD SYSTEMS OUT	\$ 1,000.00
1001.7.1 - 3rd	CONCEALMENT AND OBSTRUCTION AND/OR IMPAIRMENT	\$ 1,000.00
1001.7.2 - 3rd	NO CLEAR SPACE AROUND HYDRANT	\$ 1,000.00
1001.7.3 - 3rd	STANDPIPE HOSE STATIONS, OUTLETS AND PORTABLE EXT	\$ 1,000.00
1001.7.4 - 3rd	FIRE ALARM INITIATING DEVICES, SIGNALING DEVICES,	\$ 1,000.00
1001.8 - 3rd	EQUIPMENT AND HYDRANT NOT CLEARLY MARKED	\$ 1,000.00
1006.1 - 3rd	NO VENT HOOD & DUCT SYSTEM	\$ 1,000.00
1006.2.1 - 3rd	NO APPROVED AUTOMATIC FIRE EXTINGUISH SYSTEM	\$ 1,000.00
1006.2.3.1 - 3rd	EXTENT OF PROTECTION OR AUTO EXTINGUISH SYSTEM	\$ 1,000.00
1006.2.4.1P1 - 3rd	NO AUTOMATIC, FUEL, OR ELECTRIC SHUT-OFF	\$ 1,000.00
1006.2.4.1P2 - 3rd	MANUALLY OPERATED RESET SHUTOFF VALVE OR SWITCHES	\$ 1,000.00
1006.2.8- P1 - 3rd	DEFECT VENT SYSTEM NO CLASSIFIED GREASE FILTERS	\$ 1,000.00
1006.2.8- P2 - 3rd	GREASE EXTRACTOR NOT UTILIZED OR DEFECTIVE	\$ 1,000.00
1006.2.8- P3 - 3rd	HOOD AND DUCT SYSTEM NOT PROPERLY CLEANED	\$ 1,000.00
1006.2.8- P4 - 3rd	EXTINGUISH SYSTEM NOT INSPECTED	\$ 1,000.00
1006.2.8- P5 - 3rd	FUSIBLE LINK AND AUTO SPRINKLER HEADS NOT REPLACED	\$ 1,000.00
1007.2.1.1 - 3rd	NO APPROVED FIRE ALARM SYSTEM INSTALLED	\$ 1,000.00
1007.3.2 - 3rd	UNLISTED OR UNAPPROVED FIRE PROTECT AND COMPONENTS	\$ 1,000.00
1007.3.3.1 - 3rd	INSUFFICIENT OR LACK OF MANUAL FIRE ALARM SYSTEMS	\$ 1,000.00
1007.3.3.2 - 3rd	NO ACCESS TO FIRE ALARM CONTROL UNITS	\$ 1,000.00
1007.3.4.1 - 3rd	NO FIRE ALARM ACCEPTANCE & CERTIFICATION DOCUMENTS	\$ 1,000.00
101.2 - 3rd	FAIL TO COMPLY W/NATIONALLY RECOGNIZED STANDARDS	\$ 1,000.00
103.1.1 - 3rd	FAILURE TO UTILIZE PROFESSIONAL ENGINEERS, SPEC	\$ 1,000.00
104.1.2 - 3rd	OBSTRUCTION OF FIRE SCENE OPERATIONS	\$ 1,000.00
105 - 3rd	FAILURE TO OBTAIN A PERMIT	\$ 1,000.00
105.7 -SS1 - 3rd	PERMIT UTILIZED BY UNAUTHORIZED PERSON	\$ 1,000.00
105.7 -SS2 - 3rd	PERMIT UTILIZED BY UNAUTHORIZED LOCATION	\$ 1,000.00
105.7 -SS3 - 3rd	FAILURE TO FOLLOW CONDITIONS OF PERMIT	\$ 1,000.00
105.7 -SS4 - 3rd	FAILURE/REFUSAL OR NEGLIGENCE TO COMPLY	\$ 1,000.00
105.7 -SS5 - 3rd	FALSE STATEMENT OR MISREPRESENTATION IN APPLICATN	\$ 1,000.00
105.7 -SS6 - 3rd	PERMIT ISSUED IN ERROR OR IN VIOLATION OF	\$ 1,000.00
105.8 -SSA.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR AEROSOL PRODUCTS	\$ 1,000.00
105.8 -SSA.2 - 3rd	FAILURE TO OBTAIN PERMIT FOR AIRCRAFT REFEUELING	\$ 1,000.00
105.8 -SSA.3 - 3rd	FAILURE TO OBTAIN PERMIT FOR AIRCRAFT REPAIR HANGER	\$ 1,000.00
105.8 -SSA.4 - 3rd	FAILURE TO OBTAIN PERMIT FOR ASBESTOS REMOVAL	\$ 1,000.00
105.8 -SSA.5 - 3rd	FAILURE TO OBTAIN PERMIT FOR AUTOMOBILE WRECKING	\$ 1,000.00
105.8 -SSB.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR A BATTERY SYSTEM	\$ 1,000.00
105.8 -SSB.2 - 3rd	FAILURE TO OBTAIN PERMIT FOR BOWLING PIN OR ALLEY	\$ 1,000.00
105.8 -SSC.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR CANDLES OR OPEN FLAME	\$ 1,000.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
105.8 -SSC.2 - 3rd	FAILURE TO OBTAIN PERMIT FOR CARNIALS AND FAIRS	\$ 1,000.00
105.8 -SSC.3 - 3rd	FAILURE TO OBTAIN PERMIT FOR CELLULOSE NITRATE	\$ 1,000.00
105.8 -SSC.4 - 3rd	FAILURE TO OBTAIN PERMIT FOR CELLULOSE NITRATE	\$ 1,000.00
105.8 -SSC.5 - 3rd	FAILURE TO OBTAIN PERMIT FOR COMBUSTIBLE FIBER	\$ 1,000.00
105.8 -SSC.6 - 3rd	FAILURE TO OBTAIN PERMIT FOR COMBUSTIBLE MATERIAL	\$ 1,000.00
105.8 -SSC.7 - 3rd	FAILURE TO OBTAIN PERMIT FOR COMPRESSED GASES	\$ 1,000.00
105.8 -SSC.8 - 3rd	FAILURE TO OBTAIN PERMIT FOR COMMERCIAL RUBBISH-HAUL	\$ 1,000.00
105.8 -SSC.9 - 3rd	FAILURE TO OBTAIN PERMIT FOR CRYOGENS	\$ 1,000.00
105.8 -SSD.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR DRY CLEANING PLANTS	\$ 1,000.00
105.8 -SSD.2 - 3rd	FAILURE TO OBTAIN PERMIT FOR DUST PRODUCING	\$ 1,000.00
105.8 -SSE.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR EXPLOSIVES OR BLASTING	\$ 1,000.00
105.8 -SSF.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR FIRE HYDRANTS	\$ 1,000.00
105.8 -SSF.2 - 3rd	FAILURE TO OBTAIN PERMIT FOR FIREWORKS	\$ 1,000.00
105.8 -SSF.3 - 3rd	FAILURE TO OBTAIN PERMIT FOR FLAMMABLE OR COMBUSTIBLE	\$ 1,000.00
105.8 -SSF.4 - 3rd	FAILURE TO OBTAIN PERMIT FOR FRUIT RIPENING	\$ 1,000.00
105.8 -SSF.5 - 3rd	FAILURE TO OBTAIN PERMIT FOR FUMIGATION OR THERMAL	\$ 1,000.00
105.8 -SSH.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR HAZARDOUS MATERIALS	\$ 1,000.00
105.8 -SSH.2 - 3rd	FAILURE TO OBTAIN PERMIT FOR HIGH-PILED COMBUSTIBLES	\$ 1,000.00
105.8 -SSH.3 - 3rd	FAILURE TO OBTAIN PERMIT FOR HOT-WORK OPERATIONS	\$ 1,000.00
105.8 -SSI.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR LIQUIFIED PETROLEUM	\$ 1,000.00
105.8 -SSI.2 - 3rd	FAILURE TO OBTAIN PERMIT FOR LIQUID OR GAS FUELED	\$ 1,000.00
105.8 -SSI.3 - 3rd	FAILURE TO OBTAIN PERMIT FOR LUMBER YARDS	\$ 1,000.00
105.8 -SSM.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR MAGNESIUM WORKING	\$ 1,000.00
105.8 -SSM.2 - 3rd	FAILURE TO OBTAIN PERMIT FOR MALL COVERED	\$ 1,000.00
105.8 -SSM.3 - 3rd	FAILURE TO OBTAIN PERMIT FOR MOTOR VEHICLE FUEL	\$ 1,000.00
105.8 -SSO.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR OPEN BURNING	\$ 1,000.00
105.8 -SSO.2 - 3rd	FAILURE TO OBTAIN PERMIT FOR OPEN BURNING	\$ 1,000.00
105.8 -SSO.3 - 3rd	FAILURE TO OBTAIN PERMIT FOR OVENS, INDUSTRIAL	\$ 1,000.00
105.8 -SSP.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR PARADE FLOATS	\$ 1,000.00
105.8 -SSP.2 - 3rd	FAILURE TO OBTAIN PERMIT FOR PLACES OF ASSEMBLY	\$ 1,000.00
105.8 -SSP.3 - 3rd	FAILURE TO OBTAIN PERMIT FOR PYROTECHNICAL SPECIAL	\$ 1,000.00
105.8 -SSR.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR RADIOACTIVE MATERIALS	\$ 1,000.00
105.8 -SSR.2 - 3rd	FAILURE TO OBTAIN PERMIT FOR REFRIGERATION EQUIPMENT	\$ 1,000.00
105.8 -SSR.3 - 3rd	FAILURE TO OBTAIN PERMIT FOR REPAIR GARAGES	\$ 1,000.00
105.8 -SSS.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR SPRAYING OR DIPPING	\$ 1,000.00
105.8 -SST.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR TEMPOARY MEMBRANE	\$ 1,000.00
105.8 -SST.2 - 3rd	FAILURE TO OBTAIN PERMIT FOR TIRE STORAGE	\$ 1,000.00
105.8 -SSW.1 - 3rd	FAILURE TO OBTAIN PERMIT FOR WOOD PORDUCTS	\$ 1,000.00
1101.1 - 3rd	GENERAL SAFETY PRECAUTIONS NOT PRACTICED	\$ 1,000.00
1101.3 - P1 - 3rd	NO PERMIT ISSUED AS REQUIRED	\$ 1,000.00
1101.3 - P2 - 3rd	NO PLAN SHOWING LOCATION/DIMENSIONS OR TIRE	\$ 1,000.00
1102.2.2 - 3rd	FREE STANDING INCINERATORS IMPROPERLY CONSTRUCTED	\$ 1,000.00
1102.2.3 - 3rd	FREE STANDING INCINERATORS IMPROPERLY LOCATED/BLDG	\$ 1,000.00
1102.2.4 - 3rd	INCINERATORS NOT PROPERLY MAINTAINED	\$ 1,000.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
1102.3.2 - 3rd	NO OPEN BURNING NOTIFICATION TO GUAM FIRE DEPT	\$ 1,000.00
1102.3.3 - 3rd	NO OPEN BURNING OF PAPER PRODUCTS	\$ 1,000.00
1102.3.4 - 3rd	TIME & ATMOSPHERIC RESTRICTIONS	\$ 1,000.00
1102.3.5 - 3rd	MINIMUM DISTANCE REQUIREMENT FOR OPEN BURNING	\$ 1,000.00
1102.3.6 - 3rd	NO FIRE EXT EQUIPMT AVAILABLE AT OPEN BURNING SITE	\$ 1,000.00
1102.3.7 - 3rd	UNATTENDED OPEN BURNING	\$ 1,000.00
1103.2.1.3 - 3rd	UNAPPROVED CONTAINERS FOR STORAGE OF OILY RAGS	\$ 1,000.00
1103.3.5 - 3rd	OUTSIDE STORAGE	\$ 1,000.00
1103.3.5.1 - 3rd	OUTSIDE STORAGE OF COMBUSTIBLE MATERIALS LOCATED	\$ 1,000.00
1103.3.6.2 - 3rd	STORAGE OF INDIVIDUAL PILES OF TIRES IN EXCESS	\$ 1,000.00
1103.3.6.3 - 3rd	IMPROPER SPACING (CLEAR SPACE LESS THAN 40 FEET)	\$ 1,000.00
1109.1 - 3rd	IGNITION SOURCES NOT IN COMPLIANCE WITH SECT 1109	\$ 1,000.00
1109.2 - 3rd	IMPROPER CLEARANCE BETWEEN IGNITION SOURCES	\$ 1,000.00
1109.3 - 3rd	PORTABLE OR OPEN FLAME DEVICES IMPROPERLY ENCLOSED	\$ 1,000.00
1109.4 - 3rd	SMOKING	\$ 1,000.00
1109.4.1 - 3rd	DESIGNATED AREAS - NO SMOKING SIGNS	\$ 1,000.00
1109.4.2 - 3rd	CONTROLLED USE (HAZARDOUS ENVIRONMENT CONDITIONS)	\$ 1,000.00
1109.5 - 3rd	IMPROPER DISCARDED BURNING OBJECTS	\$ 1,000.00
1109.6 - 3rd	IMPROPER DISCARDED HOT ASHES & SPONT IGNITION SRCS	\$ 1,000.00
1109.7 - 3rd	CHIMNEYS NOT MAINTAINED/UTILIZED WITH SPARK	\$ 1,000.00
1109.8.2 - 3rd	USE OF CANDLES & OPEN FLAME & DECORATIVE DEVICES	\$ 1,000.00
1109.8.2-S10 - 3rd	SHADES (IF USED) NOT MADE OF NON-COMBUSTIBLE	\$ 1,000.00
1109.8.2-SS1 - 3rd	CLASSES I AND II LIQUIDS AND L.P. GAS SHALL NOT BE	\$ 1,000.00
1109.8.2-SS2 - 3rd	LIQUID-OR SOLID-FUELED LIGHTING DEVICES MORE THAT	\$ 1,000.00
1109.8.2-SS3 - 3rd	DEVICES OR HOLDER NOT PREVENTING THE SPILLAGE OF	\$ 1,000.00
1109.8.2-SS4 - 3rd	THE DEVICE OR HOLDER NOT RETURNING TO ITS UPRIGHT	\$ 1,000.00
1109.8.2-SS5 - 3rd	FLAME NOT ENCLOSED	\$ 1,000.00
1109.8.2-SS6 - 3rd	CHIMNEYS NOT MADE OF NONCOMBUSTIBLE MATERIALS AND/	\$ 1,000.00
1109.8.2-SS7 - 3rd	FUEL CANISTERS NOT SAFELY SEALED FOR STORAGE	\$ 1,000.00
1109.8.2-SS8 - 3rd	STORAGE/HANDLING OF COMBUSTIBLE MATERIALS NOT IN	\$ 1,000.00
1109.8.2-SS9 - 3rd	SHADES (IF USED) NOT MADE OF NON-COMBUSTIBLE	\$ 1,000.00
1109.8.3 - 3rd	DURING RELIGIOUS CEREMONIES,LIGHTED HANDHELD CNDLS	\$ 1,000.00
1109.8.4 - 3rd	ADEQUATE SAFETY PRECAUTIONS-THEATRICAL PERFORMACES	\$ 1,000.00
1109.9.1 - 3rd	FLAMING FOOD & BEV PREPARATION	\$ 1,000.00
1109.9.2 - 3rd	IMPROPER DISPENSING OF FLAMMABLE & COMBUSTIBLE LIQ	\$ 1,000.00
1109.9.2.1 - 3rd	CONTAINERS IMPROPERLY OR NOT SECURED	\$ 1,000.00
1109.9.2.2 - 3rd	IMPROPER SERVING OF FLAMING FOODS OR BEVERAGES	\$ 1,000.00
1109.9.3 - 3rd	FLAMING FOODS/BEVERAGES NOT PREPARED NEXT TO TABLE	\$ 1,000.00
1109.9.4 - 3rd	PREPARER OF FLAMING FOOD/BEVERAGE DOESNT HAVE WET	\$ 1,000.00
1110.2 - 3rd	FAILURE TO REMOVE ALL COMB & HAZARD MATERIALS	\$ 1,000.00
1110.3 - P1 - 3rd	NO ACCUMULATION OF COMBUSTIBLE OR HAZARDOUS MATERL	\$ 1,000.00
1110.3 - P2 - 3rd	VACANT BLDG/PROPERTY NOT MAINTAINED/SECURED	\$ 1,000.00
1111.2.1 - 3rd	REQUIRED FIRE ASSEMBLIES NOT MAINTAINED/IDENTIFIED	\$ 1,000.00
1111.2.2 - 3rd	FIRE ASSEMBLIES OBSTRUCTED/IMPAIRED FROM PROPER	\$ 1,000.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
1203 - 3rd	MEANS OF EGRESS OBSTRUCTED OR RENDERED HAZARDOUS	\$ 1,000.00
1204.1 - 3rd	AISLES NOT PROVIDED FROM ALL OCCUPIED PORTIONS	\$ 1,000.00
1204.2.1 - 3rd	AISLE WIDTH NOT IN ACCORDANCE WITH SECTION 1204.2	\$ 1,000.00
1204.2.2-SS1 - 3rd	IN AREAS SERVING EMPLOYEES ONLY, MINIMUM WIDTH 24	\$ 1,000.00
1204.2.2-SS2 - 3rd	IN PUBLIC AREAS OF GROUPS B AND M CLEAR AISLE WIDT	\$ 1,000.00
1205 - 3rd	FAILURE TO MAINTAIN FIRE ESCAPES IF APPROVED	\$ 1,000.00
1206 - 3rd	EMERGENCY ESCAPE OR RESCUE WINDOWS, DOORS OR WELLS	\$ 1,000.00
1207.2A - 3rd	EXIT DOORS NOT PIVOTED/SIDE SWINGING TYPE	\$ 1,000.00
1207.2B - 3rd	EXIT DOORS NOT SWINGING IN DIRECTION OF TRAVEL	\$ 1,000.00
1207.2C - 3rd	EXIT DOORS NOT SWINGING TO FULL-OPEN POSITION	\$ 1,000.00
1207.3 -P1 - 3rd	UNABLE TO OPEN EXIT DOOR W/O KEY/EFFORT A/O EXIT	\$ 1,000.00
1207.3 -P2 - 3rd	MANUALLY OPERATED EDGE-OR SURFACE-MOUNTED FLUSH	\$ 1,000.00
1207.4 - 3rd	IMPROPER INSTALLATION OF PANIC HARDWARE	\$ 1,000.00
1207.4 - P1 - 3rd	IMPROPERLY INSTALLED PANIC HARDWARE	\$ 1,000.00
1207.4 - P2 - 3rd	IMPROPERLY INSTALLED PANIC HARDWARE WHEN BALANCE	\$ 1,000.00
1207.5 - 3rd	IMPROPER/LACK OF MAINTENANCE OF SPECIAL EGRESS	\$ 1,000.00
1207.6 - 3rd	EXIT DOORS NOT READILY DISTINGUISHABLE OR EASILY	\$ 1,000.00
1210.2 - 3rd	BARRIERS PROVIDED IN EXIT STAIRWELLS TO PREVENT	\$ 1,000.00
1210.3 - 3rd	STORAGE PROHIBITED UNDER EXIT STAIRWAYS(SEE EXCPT)	\$ 1,000.00
1210.4 - 3rd	APPROVED STAIRWAY IDENTIFICATION SIGNS MISUSED	\$ 1,000.00
1211.1 - 3rd	NO MEANS OF EGRESS ILLUMINATION (GENERAL)	\$ 1,000.00
1211.2 - 3rd	EMERGENCY POWER EQUIPMENT USED FOR MEANS OF EGRESS	\$ 1,000.00
1212.2 - 3rd	INADEQUATE OR NO EXIT SIGNS POSTED AS REQUIRED	\$ 1,000.00
1212.3 - 3rd	IMPROPER EXIT SIGN GRAPHICS AND/OR SIZE	\$ 1,000.00
1212.4 - 3rd	EXIT SIGNS NOT INTERNALLY/EXTERNALLY ILLUMINATED	\$ 1,000.00
1212.5 - 3rd	EXIT SIGNS NOT ILLUMINATED AT ALL TIMES	\$ 1,000.00
1212.6 - 3rd	ADDITIONAL EXIT SIGNS NOT PROVIDED	\$ 1,000.00
1212.7 - 3rd	ADDITIONAL EXIT SIGNS IMPROPERLY LOCATED	\$ 1,000.00
1212.8 - 3rd	EXIT SIGNS AND DIRECTIONAL EXIT MARKINGS CONCEALED	\$ 1,000.00
1213.1 - 3rd	DISCHARGE, DISPERSAL & REFUGE (GENERAL)	\$ 1,000.00
1213.2 - 3rd	MEANS OF EGRESS PLANS NOT POSTED WHEN REQUIRED	\$ 1,000.00
1303.1 - 3rd	EMERGENCY PLANS & STAFF TRAINING, FIRE DRILLS	\$ 1,000.00
1303.4.1 - 3rd	NO EMERGENCY PLANS PROVIDED	\$ 1,000.00
1303.4.2 - 3rd	EMERGENCY PLANS NOT SUBMITTED TO THE GFD FOR REVIEW	\$ 1,000.00
1303.4.3 - 3rd	EMERGENCY PLANS NOT REVIEWED ANNUALLY A/O UPDATES	\$ 1,000.00
2401.2 - 3rd	NO PERMITS FOR USE OF AIRPORTS,HELIPORTS&HELISTOPS	\$ 1,000.00
2403.2 - 3rd	IMPROPER CLEARANCE FOR HELIPORTS AND HELISTOPS	\$ 1,000.00
2403.3 - 3rd	NO PROVISIONS MADE FOR THE CONFINEMENT/DRAINAGE	\$ 1,000.00
2403.5.1 - 3rd	IMPROPER FIRE EXTINGUISHERS (MUST BE MINUMUM 80-B:	\$ 1,000.00
2501.10.1 - 3rd	INADEQUATE CLEAR WIDTH BETWEEN SEATING ROWS	\$ 1,000.00
2501.10.1SS1 - 3rd	INADEQUATE CLEAR SPACE FOR ROWS OF SEATING SERVED	\$ 1,000.00
2501.10.1SS2 - 3rd	INADEQUATE CLEAR SPACE FOR ROWS OF SEATING SERVED	\$ 1,000.00
2501.10.2 - 3rd	IMPROPER OR NO SEATING BONDING (SEE EXCEPTIONS)	\$ 1,000.00
2501.12 - 3rd	NON-COMBUSTABLE ASHTRAY OR MATCH RECEIVERS	\$ 1,000.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
2501.16.1 - 3rd	CAPACITY OF OCCUPANCY NOT PROPELY POSTED	\$ 1,000.00
2501.16.2 - 3rd	OCCUPANT LOAD EXCEEDED	\$ 1,000.00
2501.16.3 - 3rd	OVERCROWDING BEYOND THE APPROVED CAPACITY	\$ 1,000.00
2501.17 - 3rd	CANDLES & OTHER OPEN FLAME DEVICES	\$ 1,000.00
2501.18 - 3rd	NO EMERGENCY STANDBY PERSONNEL AS NEEDED	\$ 1,000.00
2501.3 - 3rd	NO PERMIT REQUIRED TO OPERATE A PLACE OF ASSEMBLY	\$ 1,000.00
2501.8.2 - 3rd	EXIT DOORS FROM GROUP OCCUPANCIES SHALL NOT	\$ 1,000.00
2501.9.2 - 3rd	IMPROPER AISLE WIDTH IN ASSEMBLY OCCUPANCIES	\$ 1,000.00
2504.1 - 3rd	OUTDOOR CARNIVALS/FAIRS AND CONCESSION BOOTHS	\$ 1,000.00
2504.2.2 - 3rd	FIRE APPARATUS ACCESS ROADS NOT PROVIDED	\$ 1,000.00
2504.2.3.1 - 3rd	FIRE APPLIANCES NOT PROVIDED FOR ENTIRE MIDWAY	\$ 1,000.00
2504.2.3.2 - 3rd	TRAVEL DISTANCE FOR FIRE EXTINGUISHERS exceed 75ft	\$ 1,000.00
2504.3.2 - 3rd	IMPROPER CLEARANCE FOR CONCESSION STANDS FOR COOK	\$ 1,000.00
2504.3.3 - 3rd	IMPROPER OR NO FIRE EXTINGUISHERS PROVIDED	\$ 1,000.00
2504.4.2.A - 3rd	INADEQUATE FUEL TANK CAPACITY IN REFERENCE	\$ 1,000.00
2504.4.2.B - 3rd	REFUELING TANK WHILE RIDE IN USE	\$ 1,000.00
2504.4.3 - 3rd	INTERNAL COMBUSTION POWER SOURCES IMPROPERLY/NOT	\$ 1,000.00
2504.4.4 - 3rd	IMPROPER OR NO FIRE EXTINGUISHER PROVIDED	\$ 1,000.00
2901.2 - 3rd	NO SERVICE/REPAIR GARAGE PERMIT	\$ 1,000.00
2901.3.1 - 3rd	NOT FOLLOWING PROPER STORAGE, USE, AND HANDLING	\$ 1,000.00
2901.3.2 - 3rd	NO TANK SPILL CONTROL	\$ 1,000.00
2901.4 - 3rd	IMPROPER DISPENSING OF ALL MOTOR VEHICLE FUELS	\$ 1,000.00
2901.5 - 3rd	INADEQUATE VENTILATION IN ACCORDANCE W/BLDNG CODE	\$ 1,000.00
2901.6.1 - 3rd	IMPROPER DRAINING OF MOTOR VEHICLE FUEL	\$ 1,000.00
2901.6.2 - 3rd	IMPROPER STORAGE OF LUBRICATING OIL	\$ 1,000.00
2901.6.3 - 3rd	IMPROPER OR NO CAP UTILIZED FOR TERMINATED TANK	\$ 1,000.00
2901.7.1 - 3rd	NO SMOKING/OPEN FLAMES IN AREAS USED FOR SERVICING	\$ 1,000.00
2901.7.2 - 3rd	IMPROPER WELDING OPERATIONS	\$ 1,000.00
2901.7.3 - 3rd	IMPROPER STORAGE OF OILY WASTE MATERIALS	\$ 1,000.00
2902.5.1 - 3rd	IMPROPER/NO VENT IN BLDGS. WITH BASEMENTS OR PITS	\$ 1,000.00
2902.5.2 - 3rd	IMPROPER/NO VENT PROVIDED IN BUILDINGS W/BASEMENTS	\$ 1,000.00
3203 - 3rd	TEMP. MEMBRANE STRUCTURES,TENTS&CANOPIES(PERMIT)	\$ 1,000.00
3205.2 - 3rd	IMPROPER LOCATION & PARKING	\$ 1,000.00
3208 - 3rd	NO PORTABLE FIRE EXTINGUISHERS	\$ 1,000.00
4501.3 - 3rd	NO PERMIT AS REQUIRED FOR SPRAYING OR DIPPING	\$ 1,000.00
4502.1 - 3rd	NO FIRE PROTECTION/SUPPRESSION EQUIPMENT	\$ 1,000.00
4502.2.1 - 3rd	IMPROPER MATERIALS OF SPRAY BOOTHS	\$ 1,000.00
4502.2.2 - 3rd	IMPROPER SIZE OF SPRAY BOOTHS	\$ 1,000.00
4502.2.3 - 3rd	IMPROPER INTERIOR SURFACES OF SPRAY BOOTHS	\$ 1,000.00
4502.2.5 - 3rd	IMPROPERLY INSTALLED OR NO BAFFLES IN SPRAY BOOTHS	\$ 1,000.00
4502.2.9 - 3rd	IMPROPER LIGHT FIXTURES IN SPRAY BOOTHS	\$ 1,000.00
4901.10 - 3rd	NO VISIBLE HAZARD IDENTIFICATION SIGNS POSTED	\$ 1,000.00
4901.3 - 3rd	NO PERMIT TO CONDUCT HOT WORK	\$ 1,000.00
4901.4.1 - 3rd	NO FIRE WATCH PROVIDED DURING HOT-WORK ACTIVITIES	\$ 1,000.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
4901.4.2 - 3rd	ADDITIONAL PERSONNEL NOT ASSIGNED TO FIRE WATCH	\$ 1,000.00
4901.4.3 - 3rd	NO FIRE EXTINGUISHERS PROVIDED REQUIRED	\$ 1,000.00
4901.5.2 - 3rd	HOT WORK BEING CONDUCTED IN PROHIBITED AREAS	\$ 1,000.00
4901.5.3 - 3rd	HOT WORKS AREAS NOT CLEARED OF COMBUSTIBLES	\$ 1,000.00
4901.5.5 - 3rd	HOT WORK AREAS FLOOR'S NOT PROPERLY KEPT CLEANED	\$ 1,000.00
4901.6.2 - 3rd	HOT WORK EQUIPMENT NOT INSPECTED BY USER PRIOR TO	\$ 1,000.00
4901.6.3-SS1 - 3rd	THE HOT WORK SITE NOT CLEAR OF COMBUSTIBLES OR	\$ 1,000.00
4901.6.3-SS2 - 3rd	EXPOSED CONSTRUCTION IS NOT OF NONCOMBUSTIBLE MATE	\$ 1,000.00
4901.6.3-SS3 - 3rd	OPENINGS NOT PROTECTED	\$ 1,000.00
4901.6.3-SS4 - 3rd	FLOORS NOT KEPT CLEANED	\$ 1,000.00
4901.6.3-SS5 - 3rd	EXPOSED COMBUSTIBLES ON OPPOSITE SIDE OF PARTITION	\$ 1,000.00
4901.6.3-SS6 - 3rd	FIRE WATCHES NOT ASSIGNED, EQUIPPED, OR TRAINED	\$ 1,000.00
4901.6.3-SS7 - 3rd	FIRE EXTINGUISHERS NOT VERIFIED AS OPERABLE AND	\$ 1,000.00
4901.6.4 - 3rd	NO PRE-INSPECTION OR UNSIGNED REPORT BY INDIVIDUAL	\$ 1,000.00
4901.8.2-SS1 - 3rd	NO EMERGENCY DISCONNECT SWITCH/CIRCUIT BREAKER	\$ 1,000.00
4901.8.2-SS2 - 3rd	NO "EMERGENCY DISCONNECT" MARKED AND VISIBLE FROM	\$ 1,000.00
4901.9 - 3rd	NO FIRE PROTECTION IN HOT WORK AREAS	\$ 1,000.00
5201.10 - 3rd	IMPROPER CLEARANCE FROM WEEDS/GRASS/BRUSH/TRASH/	\$ 1,000.00
5201.11 - 3rd	IMPROPER OR NO MAINTENANCE OF FUELING SYSTEM	\$ 1,000.00
5201.3 - 3rd	IMPROPER OR NO PERMIT FOR MOTOR VEHICLE FUEL	\$ 1,000.00
5201.4.1.1 - 3rd	IMPROPER DISPENSING OF COMBUSTIBLE LIQUIDS, CNG AN	\$ 1,000.00
5201.4.1.2 - 3rd	DISPENSING DEVICES IMPROPERLY LOCATED	\$ 1,000.00
5201.4.1.3 - 3rd	BULK PLANT MOTOR VEHICLE DISPENSING STATIONS	\$ 1,000.00
5201.4.2 - 3rd	IMPROPER CLEARANCE FROM STORAGE VESSELS TO ABOVE	\$ 1,000.00
5201.5.1 - 3rd	DISPENSING DEVICES IMPROPERLY PROTECTED	\$ 1,000.00
5201.5.3 - 3rd	EMERGENCY SHUT DOWN DEVICES NOT PROVIDED	\$ 1,000.00
5201.5.4 - 3rd	ELECTRICAL DISCONNECT SWITCH NOT PROVIDED	\$ 1,000.00
5201.6.2 - 3rd	ATTENDANTS NOT CONDUCTING PRIMARY FUNCTION	\$ 1,000.00
5201.6.3 - 3rd	SIGN NOT POSTED IN CONSPICUOUS LOCATION	\$ 1,000.00
5201.7 - 3rd	ELECTRICAL EQUIPMENT NOT IN ACCORDANCE WITH CODE	\$ 1,000.00
5201.8 - 3rd	SIGNS NOT POSTED AS REQUIRED WITHIN SIGHT	\$ 1,000.00
5201.9 - 3rd	PORTABLE FIRE EXTINGUISHERS NOT PROVIDED	\$ 1,000.00
8503.1 - 3rd	IMPROPER USE OF TEMPORARY WIRING	\$ 1,000.00
8503.2 - 3rd	USE OF TEMPORARY WIRING EXCEEDS TIME ALLOTTED	\$ 1,000.00
8503.3 - 3rd	UNAPPROVED MANNER UTILIZED TO ATTACH TEMPORARY	\$ 1,000.00
8504 - 3rd	ELECTRICAL HAZARD NOT CORRECTED	\$ 1,000.00
8505 - 3rd	ELECTRICAL MOTORS NOT MAINTAINED	\$ 1,000.00
8509.2 - 3rd	ACCESS TO SWITCHBOARDS & PANEL BOARDS	\$ 1,000.00
8509.3 - 3rd	DOORS TO ELECTRICAL CONTROL PANEL ROOMS	\$ 1,000.00
8702 - 3rd	NO PERMIT ISSUED TO CONDUCT ASBESTOS-REMOVAL OPS	\$ 1,000.00
8704.15 - 3rd	ACCESS TO BLDGS/HYDRANTS/OR FIRE APPLIANCES	\$ 1,000.00
8704.16 - 3rd	NO TELEPHONE PROVIDED FOR EMERGENCY USE	\$ 1,000.00
8704.2 - 3rd	FIRE DEPARTMENT ACCESS ROADS NOT ESTABLISHED	\$ 1,000.00
8704.4.1 - 3rd	FIRE PROTECTION NOT PROVIDED DURING CONSTRUCTION	\$ 1,000.00

TVB Fine Schedule (GFD) - March 6, 2013

IFC CODE	DESCRIPTION	EFF. 03/06/13
8704.4.2 - 3rd	FIRE EXTINGUISHERS NOT PROVIDED DURING CONSTRUCTN	\$ 1,000.00
8704.4.3.1 - 3rd	IMPROPER OR NO STANDPIPE SYSTEM INSTALLED	\$ 1,000.00
8704.4.3.2 - 3rd	IMPROPER TEMPORARY STANDPIPE SYSTEM REQUIRED	\$ 1,000.00
8704.4.3.3 - 3rd	FAILURE TO FOLLOW STANDPIPE INSTALLATION PROCEDURE	\$ 1,000.00
8704.5 - 3rd	ACCUMULATION OF COMBUSTIBLE DEBRIS	\$ 1,000.00
8704.8 - 3rd	SMOKING PROHIBITED	\$ 1,000.00
8705.2 - P1 - 3rd	FIRE PROTECTION SYSTEMS NOT OPERATIONAL	\$ 1,000.00
8705.2 - P2 - 3rd	FIRE WATCH NOT CONDUCTED WHEN ENTIRE FIRE PROTECTN	\$ 1,000.00
8705.3 - 3rd	MEANS OF EGRESS NOT MAINTAINED AS REQUIRED	\$ 1,000.00
8706.2 - 3rd	AUTOMATIC SPRINKLER SYSTEM RENDERED INOPERATIVE	\$ 1,000.00
8706.3 - 3rd	SUITABLE FIRE HOSE NOT ON SITE AS REQUIRED	\$ 1,000.00
8706.5 - 3rd	NO BURNING OF COMBUSTIBLE WASTE ON SITE	\$ 1,000.00
8706.6 - 3rd	NO FIRE WATCH	\$ 1,000.00
901.1 - 3rd	VIOLATION/FIRE DEPT ACCESS & WATER SUPPLY...	\$ 1,000.00
901.4.1 - 3rd	IMPROPER OR NO MARKING OF FIRE APPARATUS ACCESS	\$ 1,000.00
901.4.2 - 3rd	NO APPROVED SIGNS/NOTICES IDENTIFYING FIRE DEPT	\$ 1,000.00
901.4.3 - 3rd	FIRE PROTECTION EQUIPMENT AND FIRE HYDRANT NOT CLR	\$ 1,000.00
901.4.4 - 3rd	NO PREMISES IDENTIFICATION	\$ 1,000.00
901.4.5 - 3rd	STREETS/ROADS NOT IDENTIFIED WITH APPROVED SIGNS	\$ 1,000.00
902.2.4.1 - 3rd	THE REQUIRED WIDTH OBSTRUCTED AND/OR NOT MAINTAINED	\$ 1,000.00
902.2.4.2 - 3rd	GATES/BARRIERS IMPROPERLY INSTALLED AND/OR MAINTND	\$ 1,000.00
903.4.1.2 - 3rd	NO TESTING & MAINT OF FIRE HYDRANT SYSTEMS	\$ 1,000.00
903.4.1.3 - 3rd	TAMPERING OF FIRE HYDRANTS	\$ 1,000.00
903.4.3 - 3rd	FIRE HYDRANTS NOT PROTECTED WITH GUARD POSTS	\$ 1,000.00
903.4.6.1 - 3rd	OBSTRUCTION OF FIRE HYDRANTS	\$ 1,000.00
UFC3403 - 3rd	REQUIRED PERMIT NOT ISSUED FOR AUTOMOBILE WRECKING	\$ 1,000.00
UFC3406 - 3rd	IMPROPER ACCUMULATION OF COMBUSTIBLE RUBBISH	\$ 1,000.00
UFC3407 - 3rd	NO FIRE EXTINGUISHERS PROVIDED AS REQUIRED	\$ 1,000.00
UFC3408 - 3rd	IMPROPER STORAGE OF TIRES	\$ 1,000.00
UFC3503 - 3rd	REQUIRED PERMIT NOT ISSUED FOR COVERED MALL BLDGS	\$ 1,000.00